

# S2k Guideline: Hygienic requirements for patient beds, bed linen, bed accessories and personal protection when handling beds

## S2k Leitlinie: Hygienische Anforderungen an Patientenbetten, Bettwäsche, Bettenzubehör und an den Personenschutz beim Umgang mit Betten

### Abstract

Hospitalized patients are often more susceptible to infection than healthy people due to their illness, the presence of devices and their reduced immune defenses. At the same time, potentially pathogenic pathogens, which are often characterized by antibiotic resistance, are released into the area close to the patient, including the bed. To prevent hospital beds from becoming a source of nosocomial infections, bed linen and hospital beds, including encasings or pillows and comforters, must be disinfected before reoccupation, in contrast to hotel beds.

The guideline outlines the hygienic and ergonomic requirements for hospital beds, ensuring bed hygiene during the patient's stay and the principles of bed reprocessing, including organization, quality assurance and staff protection, in 40 recommendations.

**Keywords:** patient bed, hygienic requirement, ergonomic requirement, patient comfort, reprocessing, disinfection, chemothermal disinfection-washing procedures, final disinfection, reprocessing control, personal protection, bed linen, bed inserts, pillows, neck pillows, blanket core, encasing, barrier cover, changing, nosokomiale Infektion, MRSA, VRE, *P. aeruginosa*, *Acinetobacter*, *K. pneumoniae*; *C. difficile*; *Shigella*; *C. auris*; Norovirus

### Zusammenfassung

Krankenhauspatienten besitzen durch ihre Erkrankung, durch u.U. vorhandene Devices und auf Grund herabgesetzter Immunabwehr häufig eine höhere Infektionsanfälligkeit als Gesunde. Zugleich werden in den patientennahen Bereich einschließlich des Betts potenziell pathogene Erreger freigesetzt, die häufig durch Antibiotikaresistenzen gekennzeichnet sind. Um zu verhindern, dass Krankenhausbetten nicht zur Quelle von nosokomialen Infektionen werden, müssen Bettwäsche und Krankenhausbetten einschließlich Encasings bzw. Kissen und Bettdeckenkerne im Gegensatz zum Hotelbett vor der Neubelegung situationsgerecht desinfizierend aufbereitet werden.

In der Leitlinie werden die hygienischen und ergonomischen Anforderungen an Krankenhausbetten, die Gewährleistung der Bettenhygiene während des Patientenaufenthalts sowie die Grundsätze der Bettenaufbereitung einschließlich der Organisation, der Qualitätssicherung und des Personenschutzes in 40 Empfehlungen begründet.

**Schlüsselwörter:** Patientenbett, hygienische Anforderungen, ergonomische Anforderungen, Patientenkomfort, Aufbereitung, Desinfektion, chemothermisches Desinfektionswaschverfahren, Schlussdesinfektion, Verfahrenskontrolle, Personenschutz, Bettwäsche, Betteinlagen, Kopfkissen, Nackenstützkissen, Deckenkerne, Encasing,

Axel Kramer<sup>1</sup>  
 Julia Seifert<sup>2</sup>  
 Bernd Gruber<sup>3</sup>  
 Marianne Abele-Horn<sup>4</sup>  
 Mardjan Arvand<sup>5</sup>  
 Alexander Blacky<sup>6</sup>  
 Michael Buerke<sup>7</sup>  
 Iris Chaberny<sup>8</sup>  
 Maria Deja<sup>9</sup>  
 Steffen Engelhart<sup>10</sup>  
 Dieter Eschberger<sup>11</sup>  
 Anja Gerhardt<sup>12</sup>  
 Achim Hedtmann<sup>13</sup>  
 Julia Heider<sup>14</sup>  
 Christian Jäkel<sup>15</sup>  
 Peter Kalbe<sup>16</sup>  
 Horst Luckhaupt<sup>17</sup>  
 Wolfgang Müller<sup>18</sup>  
 Alexander Novotny<sup>19</sup>  
 Cihan Papan<sup>20</sup>  
 Hansjürgen Piechota<sup>21</sup>  
 Frank-Albert Pitten<sup>1</sup>  
 Veronika Reinecke<sup>22</sup>  
 Simone Scheithauer<sup>8</sup>  
 Dieter Schilling<sup>23</sup>  
 Walter  
 Schulz-Schaeffer<sup>24</sup>  
 Ulrich Sunderdiek<sup>25</sup>

1 German Society for General and Hospital Hygiene, Berlin, Germany

2 German Trauma Society, Berlin, Germany

Barrierebezüge, Wechsel, Hautreizung, nosokomiale Infektion, MRSA, VRE, *P. aeruginosa*, *Acinetobacter*, *K. pneumoniae*, *C. difficile*, *Shigella*, *C. auris*, Norovirus

- 3 German Nursing Council, Berlin, Germany
- 4 Paul Ehrlich Society for Infection Therapy, Munich, Germany
- 5 Robert Koch Institute, Department Infectious Diseases, Unit Hospital Hygiene, Infection Prevention and Control, Berlin, Germany
- 6 Austrian Society for Hospital Hygiene, Vienna, Austria
- 7 German Cardiac Society, Düsseldorf, Germany
- 8 German Society for Hygiene and Microbiology, Münster, Germany
- 9 German Society of Anaesthesiology and Intensive Care Medicine, Munich, Germany
- 10 Society of Hygiene, Environmental and Public Health Sciences, Müllheim, Germany
- 11 Vienna Regional Office of the Austrian Workers' Compensation Insurance, Vienna, Austria
- 12 Hohenstein Institute for Textile Innovation gGmbH (HIT), Bönningheim, Germany
- 13 Professional Association of Orthopaedic and Trauma Specialists (BVOU), German Society for Orthopaedics and Trauma, Berlin, Germany
- 14 German Society for Oral, Maxillofacial and Facial Surgery, Hofheim am Taunus, Germany
- 15 Dr. Jäkel, Medical Law, Pharmaceuticals Law, Medical Devices Law, Luebben, Germany
- 16 Professional Association of German Surgery, Berlin, Germany
- 17 German Society of Oto-Rhino-Laryngology, Head and Neck Surgery, Bonn, Germany
- 18 Former Head of the Office of the Association of the

Scientific Medical Societies  
in Germany

19 German Society for Surgery,  
Berlin, Germany

20 German Society for  
Pediatric Infectious  
Diseases, Berlin, Germany

21 German Society for Urology,  
Düsseldorf, Germany

22 German-speaking Interest  
Group of Experts for  
Infection Prevention and  
Consultants for Hospital  
Hygiene, Zurich, Switzerland

23 German Society for  
Digestive and Metabolic  
Diseases, Berlin, Germany

24 Department of  
Neuropathology, Medical  
Faculty of the Saarland  
University, Homburg/Saar,  
Germany

25 German X-ray Society and  
German Society for  
Interventional Radiology  
and Minimally Invasive  
Therapy, Berlin, Germany

## Recommendations and justification

### 1. Hygienic and ergonomic requirements for patient beds

#### 1. Recommendation

*In hospitals and rehabilitation facilities, beds should be used that satisfy the comfort of patients regarding nursing care and well-being and should be adaptable to the patient's situation through various accessories.*

**Recommendation degree:** ↑↑

**Strength of consensus:** >95%

Care beds and hospital beds are identical in terms of their features. However, the different names are an indication of the cost bearer. For example, a doctor may prescribe a hospital bed if the patient has a disability and such a bed makes everyday life easier or is medically necessary. The costs are then covered by the health insurance company. Care beds are designed for long-term nursing care. The long-term care insurance fund covers the costs if a nursing-care level is recognized and the care bed either facilitates care, alleviates the patient's complaints or helps them to be more independent [1].

The height of the head and foot ends of the classic care bed can be adjusted. It usually has lockable castors so that it can be moved when the brake is released. This is

especially important for bedridden patients, as it is the only way to change rooms and perspectives.

#### 2. Recommendation

*The bed should be risk-adapted to ensure dimensional stability, pressure relief and elasticity, and support the recovery process.*

**Recommendation degree:** ↑

**Strength of consensus:** >95%

Depending on the patient clientele, state of health and body weight of the patient, there are different requirements for the comfort and stability of the bed, which must be clarified at the latest upon admission, because they are not always met by the classic hospital bed. For example, pressure-relieving mattresses (anti-decubitus mattresses) can be used if the patient is expected to be bedridden for a long time and is at risk of developing pressure sores [2], [3]. After spinal surgery, the mattress and slatted frame should be selected in such a way that the spine retains its upright shape when lying down as it does when standing upright (standing bed). For overweight patients, beds with special stability and height adjustability may be required (heavy-duty bed). For patients who can easily fall out of bed, e.g., those with dementia, the care bed should protect them from falling out. If a bed rail is not the right solution, a very low bed can be considered (low-height bed). With a side-support bed, the angle of inclination of the long side of the bed can be

adjusted by up to 15 degrees. This can make it easier to wash in bed and prevent pressure sores. The mattress is slotted so that it can be folded. For people with disabilities, special beds are required, e.g., with increased load-bearing capacity and a wider mattress base, motorized height adjustment, motorized adjustment of the mattress base, sitting and stand-up function if necessary and the option of equipping the bed with the required accessories. Ideally, it should be clarified before hospitalization whether a special bed is required. For this purpose, beds are either kept in the facility or leased (via a hotline, for instance).

Dimensional stability primarily concerns the properties of the mattress and its spring base. According to DIN 13014 [4], a good quality mattress should have a density of at least 40. A density of 45 to 55 is considered optimal.

Pressure relief is particularly important for bedridden patients. Mattresses with point-elastic core materials react to point loads on the body and allow it to sink in more where the pressure is higher. Mattresses with a pocket spring, latex, visco-foam or gel-foam core offer particularly high point elasticity. By dividing the core into zones, the point elasticity of the mattress is further enhanced. The support areas for the heavier parts of the body are designed, for example, with holes in the core or the use of a softer material so that better sinking into the mattress surface is possible. The pressure-relieving effect of a mattress is further improved by a suitable bed base. For example, there are sprung wooden frames or point-elastic box springs with a multi-zone division, which are particularly flexible in the shoulder or hip/buttock areas and make it easier to sink deeper into the mattress for greater pressure relief [5].

It is advantageous if the covers of mattresses are designed to be elastic, for example due to elastane in the fabric; these are called stretch covers. Elasticity is also important for fitted sheets. An elastic band is usually sewn around the perimeter of the sheet, allowing it to be pulled comfortably over the mattress. It is particularly advantageous if the fitted sheet is made of an elastic textile, so that the fabric still gives when the sheet is pulled up [5].

The neck can be relieved with special neck support pillows. They usually have a special shape and are equipped with a core of pressure-relieving material. Their shape allows the sensitive neck area to be positioned in ergonomically favorably, and the pressure-relieving core ensures that the pillow surface sinks in well. This prevents tension and pain in the neck [5].

### 3. Recommendation

*The patient's thermal comfort should be ensured by water-vapor-permeable materials, comfortable bed linen, bed inserts, pillows and comforter cores.*

**Recommendation degree:** ↑↑

**Strength of consensus:** >95%

The bed furnishings are essential for restful sleep. The bedding – especially the mattress, e.g. encasings – should not provide any additional cause for sweating. Sweating in bed creates an unpleasant feeling, impairs

sleep, can promote colds and lead to painful muscular tension.

Good moisture regulation is achieved when the body is kept dry despite sweating. The body moisture is absorbed by the sheet or mattress and the bed linen or comforter and transported from there to the other side of the equipment component (–called moisture wicking). The moisture can evaporate there. Cotton is characterized by especially high moisture absorption; however, moisture is not wicked away, which leads to a damp, cool bed climate with unpleasant consequences in the event of heavy perspiration. Microfiber and silk are characterized by good moisture management. Both absorb moisture well and do not store it, but release it again quickly. Functional materials use the principle of wicking. In bedding, moisture is drawn from the inside of the material to the outside. The moisture should be distributed as quickly as possible over as large an area as possible to achieve the fastest possible evaporation. Mechanical solutions are mainly used to provide the bedding with this property. For example, double-layer materials are used to achieve rapid moisture distribution or moisture dissipation into the next layer [5]. For all materials, but especially for barrier layers such as encasings and mattress protectors, sufficient breathability of the material must be ensured to prevent moisture build-up [6]. The water-vapor transmission resistance is determined in accordance with DIN EN ISO 11092 [7].

### 4. Recommendation

*The patient bed should meet ergonomic requirements to ensure hygiene and staff protection.*

**Recommendation degree:** ↑

**Strength of consensus:** >95%

The patient bed should allow technically assisted adjustment of the bed position, be easy to move and easy to reprocess [8].

### 5. Recommendation

*The bed frame and additional parts fitted to the bed should allow cleaning and disinfection.*

**Recommendation degree:** ↑↑

**Strength of consensus:** >95%

Electrically and mechanically operated hospital beds are class 1 non-critical medical devices (MD), which means that the design of all components, including movable and additional parts, must allow cleaning and disinfection. The surfaces of the bed frame must be smooth, easy to dry, and resistant to disinfection procedures. Components that do not allow this, e.g., electric motors that are not protected against water, electronic control consoles, etc., should not be used. Components in which liquid residues can remain are not permitted. Hollow bodies used in the design must be reliably sealed so that they are liquid-tight.

A considerable amount of time is required to professionally reprocess beds fitted with butterfly screws. The four movable modules must be removed from their mountings (this requires great force) so that they can be cleaned from the underside. There are holes in the sides of the middle elements where, for example, the bed remote

control can be hung. Dirt collects here and is difficult to remove. The movable modules have so many corners, edges and crevices that the bed has to be moved up and down to reach these areas for cleaning. Blood etc. collects in the grooves of the side rails, some of which have to be pushed into each other, and this can no longer be removed. The upper ends of the side rails are made of rough rubber material and do not form a smooth, closed surface that cannot be professionally cleaned and disinfected.

## 6. Recommendation

*To protect the mattress from contamination, wipe-disinfectable, liquid- and pathogen-proof mattress covers (encasings) should be used.*

**Recommendation degree:** ↑

**Strength of consensus:** >95%

*Staphylococcus (S.) aureus*, methicillin-resistant *S. aureus*, *Pseudomonas (P.) aeruginosa*, *Enterococcus (E.) faecalis*, coliform bacteria, *Salmonella* spp., vancomycin-resistant enterococci (VRE) and *Clostridioides (C.) difficile* [9], [10], [11], [12], [13], [14], [15], [16], [17], [18], [19] have been detected on mattresses. Contaminated mattresses have been the source of outbreaks of *P. aeruginosa* [20], gentamicin-resistant *P. aeruginosa* [21], *Acinetobacter (A.) calcoaceticus*, multidrug-resistant *A. baumannii* [22], [23], [24], VRE [25], MRSA [26], [27] and OXA-48-producing *K. pneumoniae* [28]. In mattresses made of polyurethane foam in children's beds, not only the persistence but also the proliferation of *S. aureus* was detected, apparently caused by the accumulation of water-soluble substances including proteins in the polyurethane foam [29].

Encasings protect the mattress from contamination. Encasings must be impermeable to bacteria, proven by testing under exposure to moisture and pressure [30], [31], washable, wipe-disinfectable, and impermeable to liquids. Testing of the barrier function showed that even the penetration of radionuclides was prevented [32]. The encasing should at least enclose the sleeping and side surfaces [32], [33]. Easy-to-open full covers are advantageous. Encasings ensure that the mattress only needs to be reprocessed in the event of visible contamination, e.g., after damage to the encasing. Upon discharge, the covers are subjected to disinfectant wiping with the same cloth as the bed frame.

When using wipe-disinfectable, pathogen-proof drapes with reprocessing after each patient change (washing with hot water with added surfactant and chlorine bleach), the rate of *C. difficile*-associated diarrhea (CDI) was reduced by 50% [34]. The preventive effect was especially high in combination with an antibiotic-stewardship strategy (reduction of 59% [35]). As the removal of encasings with subsequent washing is likely to lead to increased wear, personnel costs, and resource consumption, wipe disinfection with a sporocidal surface disinfectant is preferable.

Because sheets do not provide sufficient protection against contamination of the mattress [36], [37], [38], the CDC/HICPAC [39] recommend cleaning and disinfect-

ing mattresses after each discharge if encasings are not used. As early as 2005, 96% of the mattresses at Greifswald University Hospital were fitted with encasings [40]. Another advantage of encasings, in contrast to cotton covers, is that there is no increase in the mite antigen concentration under the cover. The colonization with moulds and bacteria was also significantly lower under the encasing [41], [42]. The development and persistence of house dust mites and house dust mite allergens is an important factor for people with immune hypersensitivity. In cases where a person is immunocompromised, has an underlying infection or other predisposing factors such as asthma that make them susceptible to infectious diseases, allergen accumulation in the patient environment can have a strong impact on health [43], [44].

## 7. Recommendation

*It should be possible to prepare the mattress separately from the bed frame.*

**Recommendation degree:** ↑

**Strength of consensus:** >95%

For special situations, it should be possible to reprocess the mattress separately from the bed frame, e.g., using steam disinfection. This is the case, for example, if the encasing proves to be damaged when the patient is changed and the patient had an infection with a carbapenem resistant Gram-negative organism, a norovirus infection, a CDI or an infection with another critical pathogen. In cases where separate reprocessing is not possible, the mattress must be disposed of.

## 8. Recommendation

*For pillows and blankets, either pathogen-proof covers (encasings) or materials that can be reprocessed in a disinfection washing process should be used.*

**Recommendation degree:** ↑↑

**Strength of consensus:** >95%

Unless encasings are used, bed and pillow fillings should be reprocessable using the disinfection washing process, i.e., fillings with plant fibers, animal hair, down, thermolabile or poorly drying synthetic materials are therefore unsuitable [45]. At the same time, it must be ensured as a requirement for the laundry that fillings are completely dried after the washing process.

Comforters and fitted sheets are also available as a unit (e.g., "All in One") and can be washed at high temperatures. This saves time and has the advantage that every patient receives a fresh cover and comforter.

## 2. Bed reprocessing after discharge

### 9. Recommendation

*Every patient in the hospital should receive a prepared, clean bed that poses no risk of infection.*

**Recommendation degree:** ↑↑

**Strength of consensus:** >95%

Every patient has the right to a clean, disinfected bed covered with fresh linen [46], [47].

Used hospital beds are contaminated with the patient's flora (bacteria, fungi, viruses, parasites) and can become a source of nosocomial infections (NI) if they are not re-

processed appropriately after reoccupancy [47], [48]. This applies to bed linen, pillows, comforters, mattresses, grab rails and other parts of the bed within easy reach, such as electrical switches, bells, and electronic control consoles. Studies on the contamination of patient beds and outbreaks, based on contamination of the bed, mainly date from the period 1990 to 2006; the bed has since been recognized as a potential reservoir of pathogens and has lost importance as a reservoir of NI due to disinfecting reprocessing.

Contamination of the bed is especially critical in the event of colonization or infection with multi-drug resistant organisms (MDRO) and pathogens with outbreak potential. Frequently touched surfaces on and near the bed, e.g., bed controls, call buttons and bedside tables, represent an important MDRO reservoir [49], [50]. Pathogens are released to a greater extent in diseases such as pneumonia with productive cough, urinary tract infections with incontinence, gastroenteritis, and cystic fibrosis [51], [52], [53], [54]. When assessing the risk of infection, it must be considered that hospital patients are more susceptible to infection than, for instance, healthy hotel guests, due to their illness, the presence of devices, and lowered immune defenses.

If a patient is colonized or infected with MDRO, and the following patient acquires the same pathogen, the pathogen is likely to originate primarily from the previous patient's bed or immediate environment, because not all contaminated surfaces were reached by the final disinfection after discharge. In detail, however, the source of contamination remains unclear. Repeatedly, after discharge of patients who were colonized or infected with MDRO, subsequently admitted patients acquired the same pathogen due to deficiencies in the final disinfection [55], [56], [57], [58], [59], [60], [61], [62], [63]. This applied to both outbreaks and sporadic infections [61]. An analysis of 33,494 patients revealed an increased risk of acquiring MDRO when intensive care beds are occupied [64]. It is not clear from the analysis whether the bed also plays a role in this. However, the bed frame was more frequently contaminated with MDRO in infected ICU patients than in patients who were only colonized [65]. In any case, it is necessary to carefully include the area close to the patient, with the bed as the key target in the final disinfection [47].

In conclusion, unlike hotel beds, hospital beds should not only be cleaned but also disinfected to prevent colonization or infection by pathogens and their spread. Clear reprocessing instructions must be implemented for this [47], [48], [54]. The success of the reprocessing procedure should be checked and documented.

#### 10. Recommendation

*Before each new occupancy, the handle-contact surfaces of the patient bed, movement aids, positioning aids, the surface and handle-contact surfaces of the bedside cabinet, the patient telephone and other control panels, as well as the closet, should be disinfected and cleaned.*

**Recommendation degree:** ↑↑

**Strength of consensus:** >95%

The necessity of bed reprocessing is demonstrated by the detection of representatives of the bedridden patient's microflora on the bed frame as well as on the mattress and in the area close to the bed. Potentially pathogenic pathogens, often characterized by antibiotic resistance, were released in the area close to the patient, including the bed [66]. Catalano et al. [67] isolated an epidemic strain of *A. baumannii* from the bedrail during a four-month outbreak in an intensive care unit, concluding that although the bedrail per se does not explain the transmission, it shows that dry vectors can serve as secondary reservoirs. MRSA [15], [17], [68], *C. difficile* [69], [70], vancomycin-resistant enterococci (VRE) [19], [71] and *Candida auris* [72] were also detected on bedrails. The following species were detected at the following sites: *Bacillus* spp., coagulase-negative staphylococci (CoNS), *Serratia plymuthica*, *Citrobacter (C.) koseri*, *C. braakii*, *K. pneumoniae*, and *A. baumannii* found on the bedside table; at the head of the bed coagulase-negative staphylococci CoNS; *Serratia odorifera*, *Pantoea* spp., *Cronobacter* spp., and *Mucor* spp.; on the side rail of the bed CoNS, *Bacillus* spp., *Raoultella ornithinolytica*, *Shigella* spp., *Enterobacter cloacae*, *Pantoea* spp., *Serratia odorifera*, and *Haemophilus (H.) influenzae*; on the foot of the bed CoNS, *Bacillus* spp., *Enterobacter amnigenus*, *Pseudomonas luteola* and *Moellerella wisconsensis*; and on the table above the bed CoNS, *K. pneumoniae*, *Enterobacter cloacae*, *Bacillus* spp., *H. parainfluenzae* and *Shigella* spp. [73]. The MRSA infection rate was reduced by 96% ( $p < 0.0001$ ) by implementing a hospital-wide protocol for the disinfectant cleaning of surfaces close to patients [74]. In Figure 1, the surfaces to be included in disinfectant cleaning are marked in red.

#### 11. Recommendation

*After the patient has been discharged, if mattress encasings are used, they should be disinfected by wiping and checked for damage.*

**Recommendation degree:** ↑↑

**Strength of consensus:** >95%

Encasings can be disinfected by wiping with the same cloth as the bed frame. During wipe disinfection of the encasings, a visual check should be carried out to determine whether the cover is defective, soaked, or soiled [75]. If this is the case, it is removed and disposed of or reprocessed. Otherwise, the mattress may be contaminated, putting the patient at risk. The necessity of the inspection is demonstrated by a study in which 32.5% of 2,561 mattresses showed damage to the encasings. A distinction was made between 4 degrees of damage: no visible damage, minor damage that can be sealed with an approved repair patch, damage that cannot be repaired and should be replaced if possible, and severe damage with liquid flowing into the mattress and immediate replacement of the mattress [76]. Depending on the duration of bed rest and risk assessment for the release of critical pathogens, encasings should be opened for visual inspection of the mattress to determine whether liquid has penetrated. If this is the case, the encasing and the mattress should be replaced.



Figure 1: Surfaces to be disinfected before re-occupying the bed are marked in red

In the majority of bed-associated nosocomial outbreaks, damaged mattresses were the cause [77]. Bradbury et al. [78] reported that, upon visual inspection after a near-miss patient incident, 177 of 656 (27%) hospital-bed mattresses proved to be damaged and contaminated. From January 2011 to January 2016, the US Food and Drug Administration (FDA) [75] received more than 700 reports of medical mattress covers that failed to prevent blood and body fluids from entering the mattress. In response, the FDA issued a safety communication that provides recommendations to healthcare providers, healthcare facility staff, and caregivers, for the inspection, maintenance, replacement, and removal of mattresses in healthcare facilities [74]. The FDA [75] recommends that bed-managing hospitals develop a mattress inspection plan and immediately replace any mattress cover showing signs of damage or wear. Following the FDA's communications, the Joint Commission published guidance in 2018 [79] specifically stating that healthcare facilities should avoid "tears or holes in upholstery or mattresses", and "patch any holes or tears with an approved product (not tape) that can be cleaned and disinfected. It is therefore advisable to have a risk-adapted inspection plan for the beds."

### 12. Recommendation

*For disinfecting/cleaning of the bed frame, including accessories and encasings, surface disinfectants with manufacturer-independent, expert-assured effectiveness should be used.*

**Recommendation degree:** ↑↑

**Strength of consensus:** >95%

The disinfectants must meet the following requirements for use in infection-sensitive areas that go beyond the biocidal product approval [80]

- The disinfectant must have been tested singly.
- The reproducibility of the results must be confirmed by two independent laboratories. Specifications for replication of the efficacy test must be observed.
- The bactericidal and levurocidal efficacy and any additional tuberculocidal, mycobactericidal, fungicidal, sporicidal and/or virus-inactivating efficacy required as a result of the risk assessment must be documented by two independent test reports and associated expert opinions.
- The test reports must fulfill the requirements for the test method according to the current state of scientific

knowledge, consider the actual application form or technique, and have been prepared by accredited laboratories independent of the manufacturer.

- The test reports and expert opinions with recommendations for use must be scientifically evaluated by an independent expert commission for conformity with standardized requirements.

These requirements are met by products and procedures that are included in the disinfectant list of the German Association for Applied Hygiene (VAH) [81], the Austrian Society of Hygiene and Microbiology (ÖGHMP) or the Robert Koch Institute (RKI) in Berlin [82]. Products or procedures from these lists guarantee a high level of safety. Therefore, only preparations included in these lists should be used [80].

### 13. Recommendation

*If there is any indication of contamination with non-enveloped viruses, mycobacteria, bacterial spores or fungi, surface disinfectants with the appropriate spectrum of activity should be used.*

**Recommendation degree:** ↑↑

**Strength of consensus:** >95%

International consensus exists on the need for disinfectant surface cleaning in line with indications [47]. This applies especially to frequently touched surfaces close to the patient, such as the bed and its surroundings [83]. The CDC recommends, for example, that patients infected with *Candida auris* should be placed in isolation with daily disinfectant cleaning of surfaces close to the patient and final disinfection after discharge [72].

Both reviews and guidelines on preventing the transmission of, e.g., *C. difficile*, MRSA and noroviruses recommend controlled disinfectant surface cleaning as part of the prevention strategy [84], [85], [86], [87], [88], [89], [90], [91], [92], [93], [94], [95], [96], [97], [98], [99], [100], [101], [102], [103]. This is even more pronounced in outbreak situations [104], [105].

With the exception of mycobacteria, bacterial spores, fungi or non-enveloped viruses, all vegetative bacterial species (bactericidal) and yeasts (levurocidal) are killed by VAH-listed surface disinfectants [80]. Disinfectants with an additional, appropriately declared spectrum of activity may be characterized by higher cytotoxicity (depending on the active substance and/or the application concentration) [106], which may increase the risk of side effects. Therefore, surface disinfectants that include the

entire spectrum of activity should not always be used. Instead, the choice should be made based on a careful risk-benefit assessment. In case of infection with *Mycobacterium tuberculosis* or atypical mycobacteria, disinfectants with the “tuberculocidal” or “mycobactericidal” spectrum of activity should be used, especially for final disinfection and in outbreak situations [3]; the relevant information can be found in the VAH list [81]. After contamination with bacterial spores (e.g., infection with *C. difficile*), the spectrum of activity should be sporicidal, for non-enveloped lipophilic viruses (e.g., infection by noroviruses, rota viruses or adenoviruses) the spectrum of activity should be limited to virucidal Plus, for non-enveloped hydrophilic viruses (e.g., infection by HEV, HAV, parvoviruses, boca viruses, picornaviruses) it should be virucidal, and for molds (e.g., pulmonary aspergillosis) it should be fungicidal [47], [107]. In the rare case of disinfection ordered by the authorities in accordance with Section 18 (1) sentence 1 no. 1 of the Infection Protection Act, surface disinfectants from the Robert Koch Institute Berlin disinfectant list should be used [82].

For reprocessing, the requirements for the general hygienic reprocessing of medical devices in accordance with Section 4 (1) of the Medical Devices Operator Ordinance (MPBetreibV) must be met, as well as the requirements for special hygienic reprocessing in accordance with Section 4 (2) MPBetreibV [108]. If country-specific regulations on bed reprocessing exist, these must be complied with [109].

#### 14. Recommendation

*The bed linen (comforter cover, pillowcase and sheets) should be disinfected before each new occupancy.*

**Recommendation degree:** ↑↑

**Strength of consensus:** >95%

This is necessary to protect patients from infection. In addition to the risk of infection from contaminated laundry, microbial proliferation on textiles can cause unpleasant odors and skin irritation, and reduces the tear resistance of textiles [107], [108].

#### 15. Recommendation

*Reprocessed bed linen should be visually and functionally flawless and treated in such a way that patients are not endangered by detergent residues at irritating concentrations.*

**Recommendation degree:** ↑↑

**Strength of consensus:** >95%

As detergent residues can cause skin irritation [110], [111], [112], [113], it is advisable to ask the laundry whether their quality assurance system excludes excessive detergent residues, e.g., by using rinse test fabrics. The following values are recommended as guides in the rinse test fabric: pH value 4.3–8.3; organic incrustation <1.0%; inorganic incrustation <1.0%; anionic surfactants <200 µg/g; nitrogen surfactants <450 µg/g for PES/CO (Polyester/Baumwolle) blends, and <600 µg/g for cotton [114]. Detergent stains can be an indication of excessive residues. Laundries should ensure that the reprocessed bedding no longer has any residual alkalinity by acidifying the rinsing bath accordingly and using sufficient rinsing

baths. If a skin-irritating effect is suspected, it is recommended that the reprocessing process in the reprocessing laundry is checked by a representative of the hygiene staff. In one such suspected case, the pronounced cytotoxicity of the reprocessed laundry was demonstrated in a cell culture test. After checking the procedures in the laundry and changing the reprocessing process (acidification in the rinsing bath and subsequent rinsing baths), the cytotoxicity was no longer present (Kramer, unpublished). Craemer and Humphries [54] described problems resulting from inadequate cleaning of hospital beds. They argued that bed linen should be reprocessed once a week if patients are at specific risk of infection. Optimal bed linen was described as that which can be easily washed and dried and has the lowest potential to harbor microorganisms. In addition, it was reiterated that pillows and mattresses deserve the most attention due to their proximity to the patient. The correct maintenance of positioning presses and trolleys as part of the reprocessing process was highlighted as an area that should also be considered as part of the prevention strategy.

#### 16. Recommendation

*Sheets and bed linen should be completely removed after each patient change and collected directly in sufficiently resistant and clearly labeled laundry bags without intermediate storage.*

**Recommendation degree:** ↑↑

**Strength of consensus:** >95%

After discharge, the bed linen is completely removed and collected without intermediate storage. This is to ensure that pathogens adhering to the bed linen are not spread further. Coordination between the work areas in which the linen is produced and the laundry is required for correct collection (e.g., wet laundry transport with additional liquid-tight bag) and labeling [40].

#### 17. Recommendation

*Sheets and bed covers should be reprocessed after each patient change using a validated disinfecting washing process.*

**Recommendation degree:** ↑↑

**Strength of consensus:** >95%

On dry textiles, pathogens retain their ability to multiply for days to weeks, e.g., *E. faecium* up to 51 d, *E. faecalis* >90 d, VRE >80 d, MRSA >206 d, *Streptococcus pyogenes* >206 d, *A. baumannii* >60 d, *Escherichia coli* >206 d, *K. pneumoniae* >56 d, *P. aeruginosa* >56 d, *Stenotrophomonas maltophilia* >52 d, *A. calcoaceticus anitratus* >25 d, *A. calcoaceticus lwoffii* 7 d, *A. niger* >30 d, *C. albicans* 120 d, *Cryptococcus neoformans* >30 d, hepatitis A virus (on paper) >60 d, hepatitis E virus (on stainless steel) >28 d, rotavirus >7 d, influenza A virus 14 d, papillomavirus <7 d, hepatitis B virus >14 d [115]. SARS-CoV-2 was infectious on clothing at 20 °C for up to 14 d [116]. Scabies mites persist on bed linen for 24–36 h [117]. The role of bed linen as a source of contamination for scabies became evident, for example, when bed linen was returned from the laundry that had not been properly reprocessed, resulting in a nosocomial outbreak of scabies [118]. *S. aureus*, *E. faecium*, *P.*

*aeruginosa* and *Enterobacter aerogenes* can withstand temperatures of 60 °C in standard washing procedures [119]. Therefore, bed linen must be reprocessed in a validated disinfecting washing process to safely inactivate adhering pathogens. For chemothermal disinfection-washing procedures, the concentration of the respective detergent and disinfectant, the solvent ratio during the disinfection phase, the temperature and the temperature holding time as well as the effective range, are specified [81], [82]. Laundry disinfection processes are predominantly peracetic acid-based processes with temperatures between 60 and 70 °C; however, 40 °C processes are also available [81], [82].

As expected, all samples of used bed linen were microbially contaminated with a mean load of 23 colony-forming units (CFU)/25 cm<sup>2</sup> (range 1–191 CFU). 57% of the species were potentially pathogenic [120], which poses a particular risk for patients with immune deficiencies.

### 18. Recommendation

*Pillows and comforter cores (inlets) should only be disinfected on an ad hoc basis and in accordance with a risk assessment at specified intervals.*

**Recommendation degree:** ↑↑

**Strength of consensus:** >95%

Soiling, moisture penetration, sweat marks, odor, defects and contamination with critical pathogens can be reasons for a necessary change. Defective pillow and comforter cores must be repaired or sorted out and replaced. Storage capacity is required for this purpose.

The decision to carry out disinfecting reprocessing on an ad hoc basis should be based on a risk assessment by the ward management and the hygiene team. In the case of known colonization or infection with MDRO or with pathogens of transmissible infections, disinfecting reprocessing is indicated after discharge in risk areas (e.g., intensive care, isolation unit, transplant units, patients with chronic wounds, catheters or incontinence problems). The following findings justify the need for the risk assessment. *Acinetobacter* spp. [121], [122], *Aspergillus* spp., *Aureobasidium pullulans* and *Rhodotorula mucilaginosa* [123] as well as MRSA [13] were detected on pillows. In a study by Lange et al. [124], 38% of hospital pillows were colonized with MRSA and coliform bacteria. After cutting open nominally fluid-tight pillows with seams from a burn unit, many were visibly contaminated with body fluids [125]. Mottar et al. [126] observed striking discrepancies in the weight of pillows in a burn center. The pillows were found to be a source of leakage, and several pathogens were isolated from inside the pillows that correlated with patient infections. Lippmann et al. [127] searched for reservoirs of infection to explain a large outbreak of 4 MRGN *K. pneumoniae* in Germany and found that positioning pillows were internally contaminated, with pathogen persistence for at least 6 months. Carbapenem-resistant *Enterobacteriaceae* were detectable on the bed frame, pillow and mattress pad [128]. No test results on microbial contamination of comforters were available in the literature.

If there is no indication of infection risk, reprocessing can be omitted after the patient has been discharged, and reduced to the defined reprocessing frequency. However, there is no evidence upon which to base a standardized interval of regular reprocessing. As the frequency is influenced by the frequency of occupancy changes and the patient clientele, it should be determined in consultation between the hygiene specialist and the ward management. For pillows, a quarterly cycle appears to be a sensible guideline. As fitted blankets are less sweaty than pillows, a six-month cycle may be sufficient. Where encasings are used, these can be wipe-disinfected; otherwise, the comforter must be reprocessed by disinfection washing.

So-called barrier cushions made of vinyl offer the highest level of safety. They differ from standard encasings in that the seams are not sewn but welded together with high frequency radio waves to achieve a seal. The lack of seam holes prevents contaminated air from penetrating via the seams. Instead, the air flows in and out of the cushion through a watertight filter that prevents the penetration of bacteria, fungi and viruses down to a size of 25 nm [129]. The pillowcase is disinfection-cleaned before reuse. When comparing 100 of these covers with 100 new nominally occlusive pillows with stitched seams, 60% of the inside of the standard covers were contaminated after 3 months of use, while none of the barrier covers were contaminated. This led to a company-wide introduction of the barrier cover and an associated reduction in infections caused by MRSA and *C. difficile* [130].

### 19. Recommendation

*If final disinfection is required, the bed and the area around the bed should be included in the disinfection cleaning process.*

**Recommendation degree:** ↑↑

**Strength of consensus:** >95%

In case of deficiencies in the final disinfection after discharge of patients with problematic pathogens, infection of the next patient with the pathogen was observed in a number of studies [47]. Further information on indications for final disinfection can be found in the recommendation of the Commission for Hospital Hygiene and Infection Prevention (KRINKO) concerning hygiene requirements for cleaning and disinfection of surfaces [47].

### 20. Recommendation

*For patients with Creutzfeldt-Jakob disease (CJD), the reprocessing procedure should be coordinated with the responsible hospital hygienist.*

**Recommendation degree:** ↑↑

**Strength of consensus:** >95%

Due to the high resistance of prions, the procedure should be decided upon depending on the risk [131], [132].

### 21. Recommendation

*Reprocessed beds should be clearly labeled as “reprocessed”.*

**Recommendation degree:** ↑↑

**Strength of consensus:** >95%

Otherwise, there is a possibility that beds that have not been prepared will be occupied by the next patient.

**22. Recommendation**

*If the patient will just be lying down for a few hours, stretchers or couches with washable and disinfectable surfaces can be used instead of a bed.*

**Recommendation degree:** ↔

**Strength of consensus:** >95%

If the length of stay is only a few hours, e.g. for outpatients, day clinics and dialysis patients, we recommend placing the patient on surfaces that can be washed and disinfected without sheets, comforters and pillows for reasons of sustainability. The nature of the bed must offer sufficient comfort. If the bed surface is provided with a fresh cover for each patient, the bed should only be wiped clean and disinfected after contamination, including all contact surfaces. Although no studies are available on this, couches/stretchers should be completely disinfected at approximately weekly intervals.

**3. Bed hygiene during the patient's stay****23. Recommendation**

*The contact surfaces close to the patient (e.g., on the bed, bedside cabinet, control elements) should be disinfected once a day.*

**Recommendation degree:** ↑

**Strength of consensus:** >95%

Since adherence to hand antisepsis varies between 9.1% and 85.2% depending on the type of ward, geographical region and team leadership [133], [134], daily disinfection of frequently touched surfaces close to patients reduces the risk of spreading nosocomial infections [47].

**24. Recommendation**

*In the case of visible contamination, the bed frame should be cleaned and disinfected promptly. Depending on the extent of the contamination, a two-stage process for cleaning and disinfection can be considered.*

**Recommendation degree:** ↑↑

**Strength of consensus:** >95%

As a basic hygiene measure, contamination with potentially pathogen-containing material, e.g., blood, secretions or excretions, should be promptly removed mechanically first by cleaning (without disinfectants due to protein fixation). Only afterward should disinfectant surface cleaning or surface disinfection be carried out (two-stage procedure) [47]. Contaminated bed linen must be changed promptly.

**25. Recommendation**

*Bed linen can be changed weekly for each patient.*

**Recommendation degree:** ↔

**Strength of consensus:** >95%

Studies on the necessary frequency of linen changes are not available. Changing the bed linen at least once a week has proven to be effective [46], [54].

**26. Recommendation**

*Visibly soiled or sweaty bed linen should be changed and reprocessed promptly.*

**Recommendation degree:** ↑

**Strength of consensus:** >95%

Independent of the possible risk of contamination due to proliferation of potential pathogens in a moist environment, reprocessing is necessary from an esthetic point of view. As contamination cannot be eliminated by disinfection, there is no alternative to replacement.

**27. Recommendation**

*Post-intervention, the patient can be returned to bed without changing bed linen.*

**Recommendation degree:** ↔

**Strength of consensus:** >95%

If the patient was only in the hospital for a short time for perioperative preparation and the bed is not contaminated, it makes sense to continue using the bed for the same patient without changing the linen, as a contribution to sustainability.

**28. Recommendation**

*In the case of antiseptic decolonization of MRSA, sheets and comforter covers should be changed daily during decolonization. Mattress and pillowcases should be subjected to wipe disinfection prior to daily re-covering.*

**Recommendation degree:** ↑↑

**Strength of consensus:** >95%

It is common practice to change the patient's clothing and washing utensils daily during antiseptis in addition to changing the bed linen [135], [136]. Otherwise, recolonization of the patient will occur.

For intensive care patients with devices, the need to change linen should be determined by the ward management together with the hygiene team following a risk assessment.

**4. Personal protection when handling beds****29. Recommendation**

*Personal protective measures should be observed when removing and collecting used laundry that is contaminated with body fluids and excretions and for patients in contact or physical isolation.*

**Recommendation degree:** ↑↑

**Strength of consensus:** >95%

According to TRBA 250 [137], these are activities of protection level 2. Therefore, protective gowns, gloves, and, depending on the pathogen, mouth, nose, and hair protection should be worn both for self-protection of the team and to prevent the further spread of nosocomial infections in the case of airborne or respiratory pathogens. Information on handling laundry from areas with an increased risk of infection can also be found in DGUV Information 203-084 [138].

**30. Recommendation**

*Before the regular technical inspection, the bed should be thoroughly cleaned and disinfected.*

**Recommendation degree:** ↑↑

**Strength of consensus:** >95%

The aim of the technical inspection is to ensure functionality as well as user and patient safety. Beds equipped with electrical systems are tested and maintained by certified customer service technicians [139], [140]. The

inspection is documented and the beds are provided with a test seal. Before the inspection, the bed should be thoroughly disinfected, as the underside of the bed frame may have been soiled and contaminated by dust with adhering pathogens and by splashes during floor cleaning.

### 31. Recommendation

*After contamination of the bed linen with hazardous drugs, occupational health and safety measures should be applied to prevent any risk to the treating/caregiver staff.*

**Recommendation degree:** ↑↑

**Strength of consensus:** >95%

The following principles must be observed [141], [142]:

- Laundry contaminated with hazardous drugs (HD), e.g., with cytostatic drugs, should only be touched with gloved hands, and the gloves must be certified for handling cytostatic drugs.
- If laundry contaminated with HD can come into contact with clothing during handling, e.g., when stripping the bed, a gown should be worn in addition to the gloves.

According to the guidelines of the Occupational Safety and Health Administration [143], laundry contaminated with HA-contaminated excretions should be treated according to the standard for bloodborne pathogens. In addition to wearing personal protective equipment, this includes

- handling laundry as little as possible and not sorting or rinsing,
- packing laundry in the place where it was used,
- packing contaminated laundry in a labeled or color-coded bag so that staff can identify the nature of the contents,
- use a bag that prevents leakage if the contaminated laundry is so wet that seepage or leakage is possible during transportation, consider double bagging if necessary.

According to OSHA [144], the contents of laundry bags with HD-contaminated laundry should be prewashed and only then should the laundry be added to other laundry for a second wash cycle. If such laundry is present, the reprocessing must be coordinated with the contracted laundry.

### 32. Recommendation

*Reprocessed, freshly made beds can be covered until they are used again.*

**Recommendation degree:** ↔

**Strength of consensus:** >95%

After reprocessing, the bed is covered with clean bed linen and, if necessary, covered to protect it from soiling and dust if it is not used for a longer period of time. Recyclable plastic sheeting is suitable for covering the bed.

## 5. Organization of bed reprocessing

### 33. Recommendation

*Bed reprocessing can be organized decentrally or centrally.*

**Recommendation degree:** ↔

**Strength of consensus:** >95%

At the beginning of the 1990s, centralized bed reprocessing was still preferred on the assumption that decentralized reprocessing resulted in uncontrollable risks of cross-infection, that there was no storage space for reprocessed beds on the ward, and that numerous errors were observed in decentralized reprocessing. When reprocessing in the patient's room, the lack of separation of clean and unclean activities and an overall unsystematic approach were observed [145].

Due to the significantly lower costs and the technical complexity of modern hospital beds, bed reprocessing is now almost exclusively carried out decentrally, even if there is still a central bed reprocessing unit. With identical reprocessing results, the total costs for centralized manual and centralized automated reprocessing are 2.9 and 4.5 times higher, respectively, compared to decentralized bed reprocessing. In addition, repairs to the bed frame are more frequent with centralized reprocessing, and the wear and tear on mattresses increases [146]. Finally, there is a risk of spreading pathogens when transporting beds to be reprocessed to the bed center. The preference for decentralized bed reprocessing is also supported by the fact that patients and visitors in the hospital are not confronted with bed transports and the load on the freight elevator caused by bed transports is eliminated. In the case of centralized reprocessing, it is desirable to equip the bed center with a bed lifting system to facilitate cleaning and maintenance work on the patient beds [8].

In the case of decentralized reprocessing, the manual reprocessing of the patient bed should be carried out on the ward level in a separate room to avoid disturbing other patients. In multi-bed rooms, another reason for separate reprocessing is that no nursing or medical activities can be carried out on other patients in the patient room during reprocessing. When planning, it is recommendable to provide a bed reprocessing room that can be conveniently used by one or more wards. The room should enable the functional separation of work processes into unclean and clean, be equipped with a dosing device for preparing disinfectant solutions, and ideally contain a bed lifting system [8].

In single-bed rooms, from a hygiene point of view, reprocessing can also be carried out in the room, because bed and patient have been in the room up to this time and dust and pathogens are not fundamentally different from those generated during daily bed-making. Even given cohort isolation, e.g., in a twin room, bed reprocessing including disinfection of other surfaces close to the patient can be carried out after discharge from the isolation unit. Once isolation has been lifted, the patient room must undergo final disinfection before being reoccupied.

If no reprocessing room is available on the ward, reprocessing can be carried out in the occupied multi-bed room as temporary solution. This procedure causes no additional infection load; however, it is a nuisance. In any case, good room ventilation must be ensured during disinfecting

reprocessing. The hygiene team should define the framework conditions for this temporary solution (choice of disinfectant, ventilation, integration into the ward routine).

#### 34. Recommendation

*Ward corridors should not be used to reprocess beds.*

**Recommendation degree:** ↑

**Strength of consensus:** >95%

There is a risk of cross-infection. At the same time, corridor use is obstructed, escape and rescue routes can be blocked and visitors are left with a poor impression.

## 6. Quality assurance of bed hygiene

#### 35. Recommendation

*In both decentralized and centralized bed reprocessing, all sub-steps of reprocessing should be determined by the persons or companies responsible for reprocessing, in coordination with hospital hygiene. All reprocessing should be carried out by trained personnel and personnel protection should be ensured.*

**Recommendation degree:** ↑↑

**Strength of consensus:** >95%

According to the Medical Devices Operator Ordinance [108], the reprocessing of MD must be specified in all sub-steps. Proper reprocessing is assumed if the joint recommendation of the KRINKO and the Federal Institute for Drugs and Medical Devices (BfArM) [147] on the "Hygiene requirements for the reprocessing of medical devices" is observed.

For both centralized and decentralized manual reprocessing, each sub-step must be defined in detail (cleaning, drying, disinfection, functional testing) and the resources must be defined and documented as work instructions (e.g., in the hygiene plan or as standard operating procedure).

A random visual and microbial inspection by hygiene staff of freshly reprocessed beds for residual soiling and microbial contamination is recommended every six months [148].

Decentralized bed reprocessing can be assigned to the collection and delivery service or the cleaning service [146]. Reprocessing by the cleaning service is the most cost-effective option [146]. A prerequisite is the training of staff, e.g., as trained bed reprocessing teams [40]. This does not exclude the possibility that nursing staff can also perform this activity outside of core working hours, for example. In any case, the type of service selected for reprocessing is responsible for the hygienic transfer. The hygiene staff are responsible for the technical instruction, monitoring and control of the reprocessing quality. Further training for state-certified disinfectors is recommended every three years for the head of the reprocessing team.

#### 36. Recommendation

*The preparation team should receive a daily report on the number of discharge beds that need to be prepared. Additionally, personnel should be available on-call to handle the preparation of unplanned discharge beds as needed.*

**Recommendation degree:** ↑

**Strength of consensus:** >95%

The preparation team should receive a daily report on the number of discharge beds that need to be prepared, broken down by category. This includes beds without infection risk, beds from high-risk areas, and beds occupied by patients with colonization or infection with MDRs or other critical pathogens. The criteria for the risk assessment should be specified in the hygiene plan to ensure appropriate risk classification. If there is uncertainty in classification, hygiene specialists can be consulted. This approach ensures a high quality of preparation. Additionally, personnel should be available on-call to handle the preparation of unplanned discharge beds as needed.

#### 37. Recommendation

*To ensure the safety of preparation, a semi-annual procedural review should be conducted for decontamination systems used for beds, bedside tables, and mattresses.*

**Recommendation degree:** ↑↑

**Strength of consensus:** >95%

The recommendations for semi-annual procedural reviews of washing systems using standardized test bodies contaminated with *E. faecium* in bovine serum albumin and mucin differ depending on the treatment of bed frames, bedside tables, and mattresses (process details in [149]). Additionally, compliance with physical procedural parameters should be verified using thermologgers.

#### 38. Recommendation

*Before utilizing a hospital laundry service, it should be verified that a hygienically safe disinfection washing procedure is used.*

**Recommendation degree:** ↑↑

**Strength of consensus:** >95%

To ensure that hygienic requirements are met, quality assurance is needed from delivery through processing to contamination-safe storage [150], [151]. Laundries and textile service providers that process textiles from hospital settings must meet the requirements of the Robert Koch Institute [82] and establish a hygiene management system. For example, the RABC system (Risk Analysis and Biocontamination Control System) certifies processing safety based on a risk analysis according to DIN EN 14065 [152]. When contracting with the laundry, it should be ensured that confirmed auditing is in place. Quality assurance according to RAL-GZ 992/2 [153] also includes the requirements according to the RKI, including unannounced external monitoring as part of the hygiene management system, as well as monitoring the preservation of textile value [RAL-GZ 992]. The use of disinfection washing procedures with efficacy area AB [82] is recommended (A=killing of vegetative bacteria including mycobacteria and fungi, including fungal spores; B=inactivation of enveloped and non-enveloped viruses).

#### 39. Recommendation

*When handling beds in the facility, damage to encasings, pillows, and mattress pads should be avoided and reported if it occurs.*

**Recommendation degree:** ↑↑

**Strength of consensus:** >95%

Care should be taken to maintain the integrity of encasings, pillows, and mattress pads to prevent the penetration of fluids and pathogens. This includes ensuring that no sharp objects, such as scissors, needles, syringes, scalpels, or other pointed items, are placed on the mattress surface [154]. Noticeable defects should be reported to the ward or department management so that corrective actions can be taken.

#### 40. Recommendation

*In case of a nosocomial infection outbreak, microbiological, virological, or parasitological testing of prepared beds may be appropriate upon recommendation by hygiene specialists.*

**Recommendation degree:** ↔

**Strength of consensus:** >95%

Since beds have been associated with outbreaks of nosocomial infections [20], [21], [22], [23], [24], [25], [26], [27], [28], [155], [156], [157], during outbreaks – especially involving pathogens with high persistence or, in the case of viruses, with high recoverability on textiles and simultaneously low infectious doses – beds of unclear origin can be included in the source investigation. Pathogens such as *C. difficile*, MRSA, *Acinetobacter* and *Klebsiella* spp., *P. aeruginosa*, noroviruses, and scabies mites (especially in cases of crusted scabies) should be considered [158]. One study reported colonization in newborns due to washed laundry contaminated with *B. cereus*. This contamination was apparently linked to a deficient washing process and high ambient temperatures in the ward [159].

As a microbiological quality indicator for prepared beds, microbial load can be determined using agar contact methods, for example, according to DIN 10113-2 [160] or DIN EN ISO 18593 [161].

## Notes

This guideline was originally published in German [162].

## Competing interests

The authors declare that they have no competing interests.

## Acknowledgement

We would like to thank Dr. rer. Biol. Hum. Cathleen Muche-Borowski, MHP, representative of the Association of the Scientific Medical Societies in Germany, and the Institute for Medical Knowledge Management, for their support in the conflict of interest assessment and the formal consensus-finding process.

## Funding

The elaboration of the guideline was not financially supported.

## Authorization by the participating societies

The version of the guideline approved by the editorial committee was sent to the boards of the participating societies mentioned above before publication and was authorized and approved by all of them in toto without changes.

## Period of validity and updating procedure

The guideline was last edited for content on 06/2024, and the validity period is set at 5 years. Comments on the update are welcome.

Contact person is Prof. em. Dr. med. habil. Axel Kramer (axel.kramer@med.uni-greifswald.de).

## Authors' ORCIDs

Kramer Axel: <https://orcid.org/0000-0003-4193-2149>  
 Seifert J: <https://orcid.org/0009-0000-8890-8934>  
 Arvand M: <https://orcid.org/0000-0002-7664-5150>  
 Chaberny I: <https://orcid.org/0000-0001-5859-3660>  
 Müller W: <https://orcid.org/0000-0003-4547-013X>  
 Novotny A: <https://orcid.org/0000-0002-8029-5958>  
 Scheithauer S: <https://orcid.org/0000-0003-0773-4739>  
 Schulz-Schaeffer W:  
<https://orcid.org/0000-0001-5886-2322>  
 Sunderdiek U: <https://orcid.org/0009-0002-0793-6146>

## Guideline report

The guideline report can be viewed in Attachment 1.

## Disclaimer: Erratum and republication

The affiliation information for author Scheithauer S was incomplete in this published version of the article. Readers are kindly referred to the republished version:

Kramer A, Seifert J, Gruber B, Abele-Horn M, Arvand M, Blacky A, Buerke M, Chaberny I, Deja M, Engelhart S, Eschberger D, Gerhardt A, Hedtmann A, Heider J, Jäkel C, Kalbe P, Luckhaupt H, Müller W, Novotny A, Papan C, Piechota H, Pitten FA, Reinecke V, Scheithauer S, Schilling D, Schulz-Schaeffer W, Sunderdiek U. S2k Guideline: Hygienic requirements for patient beds, bed linen, bed accessories and personal protection when handling beds. *GMS Hyg Infect Control*. 2026;21:Doc47.

DOI: <https://dx.doi.org/10.3205/dgkh000656>

And to the accompanying Erratum Notice:

Kramer A, Seifert J, Gruber B, Abele-Horn M, Arvand M, Blacky A, Buerke M, Chaberny I, Deja M, Engelhart S, Eschberger D, Gerhardt A, Hedtmann A, Heider J, Jäkel C, Kalbe P, Luckhaupt H, Müller W, Novotny A, Papan C, Piechota H, Pitten FA, Reinecke V, Scheithauer S, Schilling D, Schulz-Schaeffer W, Sunderdiek U. S2k Guideline: Hygienic requirements for patient beds, bed linen, bed accessories and personal protection when handling beds. *GMS Hyg Infect Control*. 2026;21:Doc48.

DOI: <https://dx.doi.org/10.3205/dgkh000657>

## Attachments

Available from <https://doi.org/10.3205/dgkh000549>

- Attachment1\_dgkh000549.pdf (176 KB)  
Guideline Report

## References

- § 40. Pflegehilfsmittel und wohnumfeldverbessernde Maßnahmen. XI. Sozialgesetzbuch - Soziale Pflegeversicherung - (Artikel 1 des Gesetzes vom 26. Mai 1994, BGBl. I S. 1014, 1015), zuletzt durch Artikel 9 des Gesetzes vom 22. Dezember 2023 (BGBl. 2023 I Nr. 408) geändert.
- Jonsson A, Lindén M, Lindgren M, Malmqvist LA, Bäcklund Y. Evaluation of antidecubitus mattresses. *Med Biol Eng Comput*. 2005 Sep;43(5):541-7. DOI: 10.1007/BF02351025
- Diesing P. Prüf- und Bewertungsmethoden für Antidekubitus-Systeme [Dissertation]. Berlin: Technische Universität Berlin; 2006. DOI: 10.14279/depositononce-1535
- DIN 13014:1977-12. Krankenhausmatratzen aus Polyätherschaum; Maße, Anforderungen, Prüfung. Berlin: Beuth; abgelaufen.
- Eigenschaften der Bettausstattung. Available from: <https://www.betten.de/lexikon/eigenschaften-der-bettausstattung.html>
- DIN CEN/TS 14237:2022-03. Textilien für Einrichtungen des Gesundheitswesens und von sozialen Diensten. Vornorm. Berlin: Beuth; 2022.
- DIN EN ISO 11092:2014-12. Textilien - Physiologische Wirkungen - Messung des Wärme- und Wasserdampfdurchgangswiderstands unter stationären Bedingungen (sweating guarded-hotplate test). Berlin: Beuth; 2014.
- Deutsche Gesellschaft für Krankenhaushygiene. Leitlinie: Anforderungen an die Bettenhygiene (IB). *Hyg Med*. 2003;28(1/2):44-6. Available from: [https://www.krankenhaushygiene.de/pdfdata/leitlinien/bettenhygiene\\_weiss.pdf](https://www.krankenhaushygiene.de/pdfdata/leitlinien/bettenhygiene_weiss.pdf)
- Ayyagari A, Chander J, Narang A, Banerjee CK, Panigrahi D, Bhakoo ON, Sarkar S. Outbreak of Salmonella worthington meningitis & septicaemia in a hospital at Chandigarh (north India). *Indian J Med Res*. 1990 Jan;91:15-7.
- Hammami A, Arlet G, Ben Redjeb S, Grimont F, Ben Hassen A, Rekik A, Philippon A. Nosocomial outbreak of acute gastroenteritis in a neonatal intensive care unit in Tunisia caused by multiply drug resistant Salmonella wien producing SHV-2 beta-lactamase. *Eur J Clin Microbiol Infect Dis*. 1991 Aug;10(8):641-6. DOI: 10.1007/BF01975816
- O'Donoghue MA, Allen KD. Costs of an outbreak of wound infections in an orthopaedic ward. *J Hosp Infect*. 1992 Sep;22(1):73-9. DOI: 10.1016/0195-6701(92)90132-6
- Rahman M. Epidemic methicillin-resistant Staphylococcus aureus (EMRSA): experience from a health district of central England over five years. *Postgrad Med J*. 1993;69 Suppl 3:S126-9; discussion S130.
- Blythe D, Keenlyside D, Dawson SJ, Galloway A. Environmental contamination due to methicillin-resistant Staphylococcus aureus (MRSA). *J Hosp Infect*. 1998 Jan;38(1):67-9. DOI: 10.1016/s0195-6701(98)90176-1
- de Andrade D, Angerami EL, Padovani CR. A bacteriological study of hospital beds before and after disinfection with phenolic disinfectant. *Rev Panam Salud Publica*. 2000 Mar;7(3):179-84. DOI: 10.1590/s1020-4989200000300007
- Rampling A, Wiseman S, Davis L, Hyett AP, Walbridge AN, Payne GC, Cornaby AJ. Evidence that hospital hygiene is important in the control of methicillin-resistant Staphylococcus aureus. *J Hosp Infect*. 2001 Oct;49(2):109-16. DOI: 10.1053/jhin.2001.1013
- French GL, Otter JA, Shannon KP, Adams NM, Watling D, Parks MJ. Tackling contamination of the hospital environment by methicillin-resistant Staphylococcus aureus (MRSA): a comparison between conventional terminal cleaning and hydrogen peroxide vapour decontamination. *J Hosp Infect*. 2004 May;57(1):31-7. DOI: 10.1016/j.jhin.2004.03.006
- Sexton T, Creamer E, Turley M, Smyth EG, Humphreys H. Persistent environmental reservoirs for vancomycin resistant enterococci requiring repeated decontamination to achieve eradication. *Br J Infect Contr*. 2002;3(3):10-3. DOI: 10.1177/175717740200300303
- McDermott H, Skally M, O'Rourke J, Humphreys H, Fitzgerald-Hughes D. Vancomycin-Resistant Enterococci (VRE) in The Intensive Care Unit in a Nonoutbreak Setting: Identification of Potential Reservoirs and Epidemiological Associations Between Patient and Environmental VRE. *Infect Control Hosp Epidemiol*. 2018 Jan;39(1):40-5. DOI: 10.1017/ice.2017.248
- Witt LS, Howard-Anderson J, Prakash-Asrani R, Overton E, Jacob JT. The role of the hospital bed in hospital-onset: A retrospective study with mediation analysis. *Infect Control Hosp Epidemiol*. 2024 May;45(5):599-603. DOI: 10.1017/ice.2023.254
- Robertson MH, Hoy G, Peterkin IM. Anti-static mattress as reservoir of pseudomonas infection. *Br Med J*. 1980 Mar;280(6217):831-2. DOI: 10.1136/bmj.280.6217.831-a
- Fujita K, Lilly HA, Kidson A, Ayliffe GA. Gentamicin-resistant Pseudomonas aeruginosa infection from mattresses in a burns unit. *Br Med J (Clin Res Ed)*. 1981 Jul;283(6285):219-20. DOI: 10.1136/bmj.283.6285.219

22. Sherertz RJ, Sullivan ML. An outbreak of infections with *Acinetobacter calcoaceticus* in burn patients: contamination of patients' mattresses. *J Infect Dis.* 1985 Feb;151(2):252-8. DOI: 10.1093/infdis/151.2.252
23. Simor AE, Lee M, Vearncombe M, Jones-Paul L, Barry C, Gomez M, Fish JS, Cartotto RC, Palmer R, Louie M. An outbreak due to multiresistant *Acinetobacter baumannii* in a burn unit: risk factors for acquisition and management. *Infect Control Hosp Epidemiol.* 2002 May;23(5):261-7. DOI: 10.1086/502046
24. Loomes S. The Journal of Infection Control Nursing. Is it safe to lie down in hospital? *Nurs Times.* 1988 Dec 7-13;84(49):63-5.
25. Falk PS, Winnike J, Woodmansee C, Desai M, Mayhall CG. Outbreak of vancomycin-resistant enterococci in a burn unit. *Infect Control Hosp Epidemiol.* 2000 Sep;21(9):575-82. DOI: 10.1086/501806
26. Ndawula EM, Brown L. Mattresses as reservoirs of epidemic methicillin-resistant *Staphylococcus aureus*. *Lancet.* 1991 Feb;337(8739):488. DOI: 10.1016/0140-6736(91)93420-e
27. van der Mee-Marquet N, Girard S, Lagarrigue F, Leroux I, Voyer I, Bloc D, Besnier JM, Quentin R. Multiresistant *Enterobacter cloacae* outbreak in an intensive care unit associated with therapeutic beds. *Crit Care.* 2006 Feb;10(1):405. DOI: 10.1186/cc4835
28. Pantel A, Richaud-Morel B, Cazaban M, Bouziges N, Sotto A, Lavigne JP. Environmental persistence of OXA-48-producing *Klebsiella pneumoniae* in a French intensive care unit. *Am J Infect Control.* 2016 Mar;44(3):366-8. DOI: 10.1016/j.ajic.2015.09.021
29. Jenkins RO, Sherburn RE. Used cot mattresses as potential reservoirs of bacterial infection: nutrient availability within polyurethane foam. *J Appl Microbiol.* 2008 Feb;104(2):526-33. DOI: 10.1111/j.1365-2672.2007.03609.x
30. Edana. Nonwoven Wet Bacterial Penetration. Nonwovens Standard Procedures (NWSP) 302.0.R0. Harmonized Nonwovens Standard Procedures Ed. 2015; latest update: June 2023. Available from: [https://www.edana.org/docs/default-source/international-standards/table-of-content-nw-standard-procedures-20210105.pdf?sfvrsn=4ede1add\\_20](https://www.edana.org/docs/default-source/international-standards/table-of-content-nw-standard-procedures-20210105.pdf?sfvrsn=4ede1add_20)
31. DIN EN ISO 22610. Operationsabdecktücher, -mäntel und Rein-Luft-Kleidung zur Verwendung als Medizinprodukte für Patienten, Klinikpersonal und Geräte - Prüfverfahren für die Widerstandsfähigkeit gegen Keimdurchtritt im feuchten Zustand (ISO/DIS 22610.2:2017); pr EN ISO 22610:2017. Berlin: Beuth; 2017.
32. Kramer A, Frank T, Höpfe H, et al. Untersuchungen zur Barrierefunktion von Schutzbezügen für Matratzen, Kissen und Decken und krankenhaushygienische Schlussfolgerungen. *Hohensteiner Rep.* 1997;(2):77-86.
33. Frank T. Experimentelle Untersuchungen zur Keimdichtigkeit von Matratzenüberzügen und Permeabilität für Radionuklide in Verbindung mit einer Akzeptanzstudie [Dissertation]. Greifswald: Universität Greifswald; 1997.
34. Hooker EA, Bochan M, Reiff TT, Blackwell C, Webb KW, Hart KW. Decreasing *Clostridium difficile* health care-associated infections through use of a launderable mattress cover. *Am J Infect Control.* 2015 Dec;43(12):1326-30. DOI: 10.1016/j.ajic.2015.07.002
35. Hooker EA, Mallow PJ, McKinney C, Gnoni ML, Fernandez Gonzales F. Use of a Launderable Bed Barrier and Antibiotic Stewardship to Decrease Hospital Onset Infections in an Acute Care Hospital: A Retrospective Pre-Post Case Study. *J Health Econ Outcomes Res.* 2019;6(3):196-202. DOI: 10.36469/001c.11149
36. Hooker EA, Allen SD, Gray LD. Comparison of rayon-tip swabs and film plates for use in collecting and quantifying bacteria on hospital bed mattresses. *Am J Infect Contr.* 2011; 39(5):E191-2. DOI: 10.1016/j.ajic.2011.04.014
37. Hooker EA, Allen S, Gray L, Kaufman C. A randomized trial to evaluate a launderable bed protection system for hospital beds. *Antimicrob Resist Infect Control.* 2012 Jul;1(1):27. DOI: 10.1186/2047-2994-1-27
38. Hooker EA, Bochan M, Reiff TT, Blackwell C, Webb KW, Hart KW. Decreasing *Clostridium difficile* health care-associated infections through use of a launderable mattress cover. *Am J Infect Control.* 2015 Dec;43(12):1326-30. DOI: 10.1016/j.ajic.2015.07.002
39. Sehulster L, Chinn RY; CDC; HICPAC. Guidelines for environmental infection control in health-care facilities. Recommendations of CDC and the Healthcare Infection Control Practices Advisory Committee (HICPAC). *MMWR Recomm Rep.* 2003 Jun;52(RR-10):1-42.
40. Böhringer P. Analyse der Bettenaufbereitung am Universitätsklinikum Greifswald unter hygienischen Gesichtspunkten und mit Berücksichtigung ökonomischer Aspekte [Dissertation]. Greifswald: Universität Greifswald; 2007. Available from: <https://d-nb.info/1021978930/34>
41. Pitten FA, Kalveram CM, Krüger U, Müller G, Kramer A. Reduktion der Besiedlung neuwertiger Matratzen mit Bakterien, Schimmelpilzen und Hausstaubmilben durch Matratzenganzbezüge [Reduction of colonization of new mattresses with bacteria, moulds and house dust mites by complete mattress covers]. *Hautarzt.* 2000 Sep;51(9):655-60. DOI: 10.1007/s001050051190
42. Pitten F, Effendy I, Kramer A, Krüger U, Scholler M. Filamentpilze und -hefen auf Matratzen mit unterschiedlichen Encasing-Überzügen. *Hohensteiner Rep.* 2002;58:36-40.
43. Platts-Mills TA, Vervloet D, Thomas WR, Aalberse RC, Chapman MD. Indoor allergens and asthma: report of the Third International Workshop. *J Allergy Clin Immunol.* 1997 Dec;100(6 Pt 1):S2-24. DOI: 10.1016/s0091-6749(97)70292-6
44. van den Bemt L, van Knapen L, de Vries MP, Jansen M, Cloosterman S, van Schayck CP. Clinical effectiveness of a mite allergen-impermeable bed-covering system in asthmatic mite-sensitive patients. *J Allergy Clin Immunol.* 2004 Oct;114(4):858-62. DOI: 10.1016/j.jaci.2004.05.069
45. Kramer A, Ruback S. Bettenaufbereitung. In: Kramer A, Assadian O, Exner M, Hübner NO, Scheithauer S, Simon A, editors. *Krankenhaus- und Praxishygiene.* 4. Aufl. München: Elsevier; 2022. p. 513-6.
46. Ruscher C. Infektionsprävention im Rahmen der Pflege und Behandlung von Patienten mit übertragbaren Krankheiten. Empfehlung der Kommission für Krankenhaushygiene und Infektionsprävention (KRINKO) beim Robert Koch-Institut. *Bundesgesundheitsblatt Gesundheitsforschung Gesundheitsschutz.* 2015 Oct;58(10):1151-70. DOI: 10.1007/s00103-015-2234-2
47. Anforderungen an die Hygiene bei der Reinigung und Desinfektion von Flächen : Empfehlung der Kommission für Krankenhaushygiene und Infektionsprävention (KRINKO) beim Robert Koch-Institut. *Bundesgesundheitsblatt Gesundheitsforschung Gesundheitsschutz.* 2022 Oct;65(10):1074-115. DOI: 10.1007/s00103-022-03576-1
48. Centers for Disease Control and Prevention. Best Practices for Environmental Cleaning in Healthcare Facilities in Resource-Limited Settings. Appendix C: Examples of high-touch surfaces in a specialized patient area. 2020. Available from: [https://www.cdc.gov/healthcare-associated-infections/hcp/cleaning-global/appendix-c.html?CDC\\_AAref\\_Val=](https://www.cdc.gov/healthcare-associated-infections/hcp/cleaning-global/appendix-c.html?CDC_AAref_Val=)
49. Murphy CR, Eells SJ, Quan V, Kim D, Peterson E, Miller LG, Huang SS. Methicillin-resistant *Staphylococcus aureus* burden in nursing homes associated with environmental contamination of common areas. *J Am Geriatr Soc.* 2012 Jun;60(6):1012-8. DOI: 10.1111/j.1532-5415.2012.03978.x

50. Dancer SJ. Controlling hospital-acquired infection: focus on the role of the environment and new technologies for decontamination. *Clin Microbiol Rev.* 2014 Oct;27(4):665-90. DOI: 10.1128/CMR.00020-14
51. Samore MH, Venkataraman L, DeGirolami PC, Arbeit RD, Karchmer AW. Clinical and molecular epidemiology of sporadic and clustered cases of nosocomial *Clostridium difficile* diarrhea. *Am J Med.* 1996 Jan;100(1):32-40. DOI: 10.1016/s0002-9343(96)90008-x
52. Panagea S, Winstanley C, Walshaw MJ, Ledson MJ, Hart CA. Environmental contamination with an epidemic strain of *Pseudomonas aeruginosa* in a Liverpool cystic fibrosis centre, and study of its survival on dry surfaces. *J Hosp Infect.* 2005 Feb;59(2):102-7. DOI: 10.1016/j.jhin.2004.09.018
53. Boyce JM, Havill NL, Otter JA, Adams NM. Widespread environmental contamination associated with patients with diarrhea and methicillin-resistant *Staphylococcus aureus* colonization of the gastrointestinal tract. *Infect Control Hosp Epidemiol.* 2007 Oct;28(10):1142-7. DOI: 10.1086/520737
54. Creamer E, Humphreys H. The contribution of beds to healthcare-associated infection: the importance of adequate decontamination. *J Hosp Infect.* 2008 May;69(1):8-23. DOI: 10.1016/j.jhin.2008.01.014
55. Huang SS, Datta R, Platt R. Risk of acquiring antibiotic-resistant bacteria from prior room occupants. *Arch Intern Med.* 2006 Oct;166(18):1945-51. DOI: 10.1001/archinte.166.18.1945
56. Shaughnessy MK, Micielli RL, DePestel DD, Arndt J, Strachan CL, Welch KB, Chenoweth CE. Evaluation of hospital room assignment and acquisition of *Clostridium difficile* infection. *Infect Control Hosp Epidemiol.* 2011 Mar;32(3):201-6. DOI: 10.1086/658669
57. Datta R, Platt R, Yokoe DS, Huang SS. Environmental cleaning intervention and risk of acquiring multidrug-resistant organisms from prior room occupants. *Arch Intern Med.* 2011 Mar;171(6):491-4. DOI: 10.1001/archinternmed.2011.64
58. Nseir S, Blazejewski C, Lubret R, Wallet F, Courcol R, Durocher A. Risk of acquiring multidrug-resistant Gram-negative bacilli from prior room occupants in the intensive care unit. *Clin Microbiol Infect.* 2011 Aug;17(8):1201-8. DOI: 10.1111/j.1469-0691.2010.03420.x
59. Cohen B, Cohen CC, Løyland B, Larson EL. Transmission of health care-associated infections from roommates and prior room occupants: a systematic review. *Clin Epidemiol.* 2017;9:297-310. DOI: 10.2147/CLEP.S124382
60. Cohen B, Liu J, Cohen AR, Larson E. Association Between Healthcare-Associated Infection and Exposure to Hospital Roommates and Previous Bed Occupants with the Same Organism. *Infect Control Hosp Epidemiol.* 2018 May;39(5):541-6. DOI: 10.1017/ice.2018.22
61. Drees M, Snyderman DR, Schmid CH, Barefoot L, Hansjosten K, Vue PM, Cronin M, Nasraway SA, Golan Y. Prior environmental contamination increases the risk of acquisition of vancomycin-resistant enterococci. *Clin Infect Dis.* 2008 Mar;46(5):678-85. DOI: 10.1086/527394
62. Mitchell BG, Dancer SJ, Anderson M, Dehn E. Risk of organism acquisition from prior room occupants: a systematic review and meta-analysis. *J Hosp Infect.* 2015 Nov;91(3):211-7. DOI: 10.1016/j.jhin.2015.08.005
63. Wu YL, Yang XY, Ding XX, Li RJ, Pan MS, Zhao X, Hu XQ, Zhang JJ, Yang LQ. Exposure to infected/colonized roommates and prior room occupants increases the risks of healthcare-associated infections with the same organism. *J Hosp Infect.* 2019 Feb;101(2):231-9. DOI: 10.1016/j.jhin.2018.10.014
64. Russotto V, Cortegiani A, Raineri SM, Iozzo P, Gregoretti C, Giarratano A. What is the risk of acquiring bacteria from prior intensive care unit bed occupants? *Crit Care.* 2017 Mar;21(1):55. DOI: 10.1186/s13054-017-1652-y
65. Russotto V, Cortegiani A, Raineri SM, Giarratano A. Bacterial contamination of inanimate surfaces and equipment in the intensive care unit. *J Intensive Care.* 2015;3:54. DOI: 10.1186/s40560-015-0120-5
66. Mody L, Washer LL, Kaye KS, Gibson K, Saint S, Reyes K, Cassone M, Mantey J, Cao J, Altamimi S, Perri M, Sax H, Chopra V, Zervos M. Multidrug-resistant Organisms in Hospitals: What Is on Patient Hands and in Their Rooms? *Clin Infect Dis.* 2019 Nov;69(11):1837-44. DOI: 10.1093/cid/ciz092
67. Catalano M, Quelle LS, Jeric PE, Di Martino A, Maimone SM. Survival of *Acinetobacter baumannii* on bed rails during an outbreak and during sporadic cases. *J Hosp Infect.* 1999 May;42(1):27-35. DOI: 10.1053/jhin.1998.0535
68. Blythe D, Keenlyside D, Dawson SJ, Galloway A. Environmental contamination due to methicillin-resistant *Staphylococcus aureus* (MRSA). *J Hosp Infect.* 1998 Jan;38(1):67-9. DOI: 10.1016/s0195-6701(98)90176-1
69. Pulvirenti JJ, Gerding DN, Nathan C, Hafiz I, Mehra T, Marsh D, Kocka F, Rice T, Fischer SA, Segreti J, Weinstein RA. Difference in the incidence of *Clostridium difficile* among patients infected with human immunodeficiency virus admitted to a public hospital and a private hospital. *Infect Control Hosp Epidemiol.* 2002 Nov;23(11):641-7. DOI: 10.1086/501987
70. Wilcox MH, Fawley WN, Wigglesworth N, Parnell P, Verity P, Freeman J. Comparison of the effect of detergent versus hypochlorite cleaning on environmental contamination and incidence of *Clostridium difficile* infection. *J Hosp Infect.* 2003 Jun;54(2):109-14. DOI: 10.1016/s0195-6701(02)00400-0
71. Bonten MJ, Hayden MK, Nathan C, van Voorhis J, Matushek M, Slaughter S, Rice T, Weinstein RA. Epidemiology of colonisation of patients and environment with vancomycin-resistant enterococci. *Lancet.* 1996 Dec;348(9042):1615-9. DOI: 10.1016/S0140-6736(96)02331-8
72. CDC. Infection Prevention and Control for *Candida auris*. 2023 Jan 17. Available from: <https://www.cdc.gov/fungal/candida-auris/c-auris-infection-control.html>
73. Maphossa V, Langa JC, Simbine S, Maússe FE, Kenga D, Relvas V, Chicamba V, Manjate A, Sacarlal J. Environmental bacterial and fungal contamination in high touch surfaces and indoor air of a paediatric intensive care unit in Maputo Central Hospital, Mozambique in 2018. *Infect Prev Pract.* 2022 Dec;4(4):100250. DOI: 10.1016/j.infpip.2022.100250
74. Watson PA, Watson LR, Torress-Cook A. Efficacy of a hospital-wide environmental cleaning protocol on hospital-acquired methicillin-resistant rates. *J Infect Prev.* 2016 Jul;17(4):171-6. DOI: 10.1177/1757177416645342
75. FDA. Covers for Hospital Bed Mattresses: Learn How to Keep Them Safe. FDA Safety Communication. 2017. Available from: <https://www.fda.gov/medical-devices/hospital-beds/covers-hospital-bed-mattresses-learn-how-keep-them-safe>.
76. Marks B, de Haas E, Abboud T, Lam I, Datta I. Uncovering the rates of damaged patient bed and stretcher mattresses in Canadian acute care hospitals. *Canadian J Infect Contr.* 2018; 33(3):171-5.
77. Li X, Lam I, Teska P, Grinstead D, Becker L. Infection risks associated with damaged mattresses and management strategy using repair patches. *Infection Control. Tips.* 2021. Available from: <https://infectioncontrol.tips/2021/05/04/infection-risks-associated-with-damaged-mattresses-and-management-strategy-using-repair-patches/>

78. Bradbury SL, Mack D, Crofts T, Ellison RT 3rd. Potential bloodborne pathogen exposure from occult mattress damage. *Am J Infect Control.* 2014 Apr;42(4):421-2. DOI: 10.1016/j.ajic.2013.10.011
79. Joint Commission Resources. The Joint Commission guideline: Environmental Infection Prevention: Guidance for Continuously Maintaining a Safe Patient Care and Survey-Ready Environment. Available from: [https://store.jcr.com/assets/1/7/redean\\_environment\\_infection\\_prevention\\_%28002%29.pdf](https://store.jcr.com/assets/1/7/redean_environment_infection_prevention_%28002%29.pdf)
80. Kommission für Krankenhaushygiene und Infektionsprävention (KRINKO). Stellungnahme der Kommission für Krankenhaushygiene und Infektionsprävention (KRINKO) zu Anforderungen an Desinfektionsmittel für den Einsatz in infektionshygienisch sensiblen Bereichen. *Epid Bull.* 2023;23:22-6. DOI: 10.25646/11517
81. Verbund für Angewandte Hygiene (VAH). Die VAH-Liste der Desinfektionsmittel. 2023. Available from: [https:// vah-online.de/de/vah-liste](https://vah-online.de/de/vah-liste)
82. Liste der vom Robert Koch-Institut geprüften und anerkannten Desinfektionsmittel und -verfahren. Stand: 31. Oktober 2017, 17. Ausgabe. Bundesgesundheitsblatt Gesundheitsforschung Gesundheitsschutz. 2017 Nov;60(11):1274-97. DOI: 10.1007/s00103-017-2634-6
83. Adams CE, Smith J, Watson V, Robertson C, Dancer SJ. Examining the association between surface bioburden and frequently touched sites in intensive care. *J Hosp Infect.* 2017 Jan;95(1):76-80. DOI: 10.1016/j.jhin.2016.11.002
84. Dancer SJ. Importance of the environment in meticillin-resistant *Staphylococcus aureus* acquisition: the case for hospital cleaning. *Lancet Infect Dis.* 2008 Feb;8(2):101-13. DOI: 10.1016/S1473-3099(07)70241-4
85. MacCannell T, Umscheid CA, Agarwal RK, Lee I, Kuntz G, Stevenson KB; Healthcare Infection Control Practices Advisory Committee-HICPAC. Guideline for the prevention and control of norovirus gastroenteritis outbreaks in healthcare settings. *Infect Control Hosp Epidemiol.* 2011 Oct;32(10):939-69. DOI: 10.1086/662025
86. Otter JA, Yezli S, Salkeld JA, French GL. Evidence that contaminated surfaces contribute to the transmission of hospital pathogens and an overview of strategies to address contaminated surfaces in hospital settings. *Am J Infect Control.* 2013 May;41(5 Suppl):S6-11. DOI: 10.1016/j.ajic.2012.12.004
87. Barclay L, Park GW, Vega E, Hall A, Parashar U, Vinjé J, Lopman B. Infection control for norovirus. *Clin Microbiol Infect.* 2014 Aug;20(8):731-40. DOI: 10.1111/1469-0691.12674
88. Calfee DP, Salgado CD, Milstone AM, Harris AD, Kuhar DT, Moody J, Auredeen K, Huang SS, Maragakis LL, Yokoe DS; Society for Healthcare Epidemiology of America. Strategies to prevent methicillin-resistant *Staphylococcus aureus* transmission and infection in acute care hospitals: 2014 update. *Infect Control Hosp Epidemiol.* 2014 Jul;35(7):772-96. DOI: 10.1086/676534
89. Siani H, Maillard JY. Best practice in healthcare environment decontamination. *Eur J Clin Microbiol Infect Dis.* 2015 Jan;34(1):1-11. DOI: 10.1007/s10096-014-2205-9
90. McDonald LC, Gerding DN, Johnson S, Bakken JS, Carroll KC, Coffin SE, Dubberke ER, Garey KW, Gould CV, Kelly C, Loo V, Shaklee Sammons J, Sandora TJ, Wilcox MH. Clinical Practice Guidelines for *Clostridium difficile* Infection in Adults and Children: 2017 Update by the Infectious Diseases Society of America (IDSA) and Society for Healthcare Epidemiology of America (SHEA). *Clin Infect Dis.* 2018 Mar;66(7):e1-e48. DOI: 10.1093/cid/cix1085
91. Han JH, Sullivan N, Leas BF, Pegues DA, Kaczmarek JL, Umscheid CA. Cleaning Hospital Room Surfaces to Prevent Health Care-Associated Infections: A Technical Brief. *Ann Intern Med.* 2015 Oct;163(8):598-607. DOI: 10.7326/M15-1192
92. Carter Y, Barry D. Tackling *C difficile* with environmental cleaning. *Nurs Times.* 2011 Sep 13-19;107(36):22-5.
93. Shaughnessy MK, Micielli RL, DePestel DD, Arndt J, Strachan CL, Welch KB, Chenoweth CE. Evaluation of hospital room assignment and acquisition of *Clostridium difficile* infection. *Infect Control Hosp Epidemiol.* 2011 Mar;32(3):201-6. DOI: 10.1086/658669
94. Weber DJ, Rutala WA. Understanding and preventing transmission of healthcare-associated pathogens due to the contaminated hospital environment. *Infect Control Hosp Epidemiol.* 2013 May;34(5):449-52. DOI: 10.1086/670223
95. Weber DJ, Rutala WA. Assessing the risk of disease transmission to patients when there is a failure to follow recommended disinfection and sterilization guidelines. *Am J Infect Control.* 2013 May;41(5 Suppl):S67-71. DOI: 10.1016/j.ajic.2012.10.031
96. Otter JA, Yezli S, French GL. The Role Played by Contaminated Surfaces in the Transmission of Nosocomial Pathogens. In: Borkow GE, editor. *Use of Biocidal Surfaces for Reduction of Healthcare Acquired Infections.* Cham: Springer; 2014. p. 27-58. DOI: 10.1007/978-3-319-08057-4\_3
97. Rosa R, Arheart KL, Depascale D, Cleary T, Kett DH, Namias N, Pizano L, Fajardo-Aquino Y, Munoz-Price LS. Environmental exposure to carbapenem-resistant *Acinetobacter baumannii* as a risk factor for patient acquisition of *A. baumannii*. *Infect Control Hosp Epidemiol.* 2014 Apr;35(4):430-3. DOI: 10.1086/675601
98. Weber DJ, Anderson D, Rutala WA. The role of the surface environment in healthcare-associated infections. *Curr Opin Infect Dis.* 2013 Aug;26(4):338-44. DOI: 10.1097/QCO.0b013e3283630f04
99. Weber DJ, Anderson DJ, Sexton DJ, Rutala WA. Role of the environment in the transmission of *Clostridium difficile* in health care facilities. *Am J Infect Control.* 2013 May;41(5 Suppl):S105-10. DOI: 10.1016/j.ajic.2012.12.009
100. Ministry of Health and Family Welfare; Government of India (MoHFW). National Guidelines for Clean Hospitals. 2015. Available from: [https://mohfw.gov.in/sites/default/files/7660257301436254417\\_0.pdf](https://mohfw.gov.in/sites/default/files/7660257301436254417_0.pdf)
101. Alblas D, Bartel A, Beaudry J, et al. Guidelines for Routine Environmental Cleaning of the Operating Room. Winnipeg: Winnipeg Regional Health Authority (WRHA); 2017.
102. Exner M, Bhattacharya S, Gebel J, Goroncy-Bermes P, Hartemann P, Heeg P, Ilshner C, Kramer A, Ling ML, Merckens W, Oltmanns P, Pitten F, Rotter M, Schmithausen RM, Sonntag HG, Steinhauer K, Trautmann M. Chemical disinfection in healthcare settings: critical aspects for the development of global strategies. *GMS Hyg Infect Control.* 2020;15:Doc36. DOI: 10.3205/dgkh000371
103. Assadian O, Harbarth S, Vos M, Knobloch JK, Asensio A, Widmer AF. Practical recommendations for routine cleaning and disinfection procedures in healthcare institutions: a narrative review. *J Hosp Infect.* 2021 Jul;113:104-14. DOI: 10.1016/j.jhin.2021.03.010
104. Otter JA, Klein JL, Watts TL, Kearns AM, French GL. Identification and control of an outbreak of ciprofloxacin-susceptible EMRSA-15 on a neonatal unit. *J Hosp Infect.* 2007 Nov;67(3):232-9. DOI: 10.1016/j.jhin.2007.07.024
105. Khanafer N, Voirin N, Barbut F, Kuijper E, Vanhems P. Hospital management of *Clostridium difficile* infection: a review of the literature. *J Hosp Infect.* 2015 Jun;90(2):91-101. DOI: 10.1016/j.jhin.2015.02.015
106. Sagripanti JL, Bonifacino A. Cytotoxicity of liquid disinfectants. *Surg Infect (Larchmt).* 2000;1(1):3-14. DOI: 10.1089/109629600321245

107. Desinfektionsmittel-Kommission im VAH. Anforderungen und Methoden zur VAH-Zertifizierung chemischer Desinfektionsverfahren. Stand: 1. September 2022. Available from: [https://vah-online.de/files/download/ebooks/eBook\\_VAH\\_Methoden\\_Anforderungen.pdf](https://vah-online.de/files/download/ebooks/eBook_VAH_Methoden_Anforderungen.pdf)
108. Medizinprodukte-Betreiberverordnung in der Fassung der Bekanntmachung vom 21. August 2002 (BGBl. I S. 3396), zuletzt durch Artikel 7 der Verordnung vom 21. April 2021 (BGBl. I S. 833) geändert.
109. Verordnung über die Errichtung und den Betrieb von Krankenhäusern (Krankenhausbetriebs-Verordnung - KhBetVO) vom 10. Juli 1995. GVBl S. 472, BRV 2128-5-5; zuletzt geändert durch § 47 Satz 2 Nr. 1 Krankenhaus-VO vom 15.9.2006, GVBl. S. 907.
110. Matthies W. Irritant dermatitis to detergents in textiles. *Curr Probl Dermatol.* 2003;31:123-38. DOI: 10.1159/000072243
111. Navratil A, Essing D. Hautirritationen durch gewaschene Wäsche aus Sicht der Textilhygiene. Teil I. Hohensteiner Wäschereiiinformation. 1990;37.
112. Navratil A, Essing D. Hautirritationen durch gewaschene Wäsche aus Sicht der Textilhygiene. Teil II. Hohensteiner Wäschereiiinformation. 1991; 38.
113. Matthis W. Hautirritationen durch gewaschene Wäsche aus Sicht der Textilhygiene. Teil III. Hohensteiner Wäschereiiinformation. 1992; 45.
114. Richtwerte nach Stand der Technik gemäß Untersuchungen Hohenstein 06.1.7-0163, Hohenstein Laboratories GmbH & CO. KG, Stand 02/2024, unveröffentlicht.
115. Kramer A, Lexow F, Bludau A, et al. Replicative capacity of microorganisms on inanimate surfaces and healthcare-associated infection risk. *Clin Microbiol Rev.* in rev.
116. Riddell S, Goldie S, Hill A, Eagles D, Drew TW. The effect of temperature on persistence of SARS-CoV-2 on common surfaces. *Virology.* 2020 Oct;17(1):145. DOI: 10.1186/s12985-020-01418-7
117. Chandler DJ, Fuller LC. A Review of Scabies: An Infestation More than Skin Deep. *Dermatology.* 2019;235(2):79-90. DOI: 10.1159/000495290
118. Thomas MC, Giedinghagen DH, Hoff GL. An outbreak of scabies among employees in a hospital-associated commercial laundry. *Infect Control.* 1987 Oct;8(10):427-9. DOI: 10.1017/s0195941700066613
119. Fijan S, Turk SŠ. Hospital textiles, are they a possible vehicle for healthcare-associated infections? *Int J Environ Res Public Health.* 2012 Sep;9(9):3330-43. DOI: 10.3390/ijerph9093330
120. Pinon A, Gachet J, Alexandre V, Decherf S, Vialette M. Microbiological contamination of bed linen and staff uniforms in a hospital. *Advanc Microbiol.* 2013;3(7):515-9. DOI: 10.4236/aim.2013.37069.
121. Weernink A, Severin WP, Tjernberg I, Dijkshoorn L. Pillows, an unexpected source of *Acinetobacter*. *J Hosp Infect.* 1995 Mar;29(3):189-99. DOI: 10.1016/0195-6701(95)90328-3
122. Mottar R, Roth M, Allen M, Gerber R, Jeffers BR. Pillow talk: examining pillow cores in a regional burn center. *Am J Infect Contr.* 2006; 34:E107-E108. DOI: 10.1016/j.ajic.2006.05.078
123. Woodcock AA, Steel N, Moore CB, Howard SJ, Custovic A, Denning DW. Fungal contamination of bedding. *Allergy.* 2006 Jan;61(1):140-2. DOI: 10.1111/j.1398-9995.2005.00941.x
124. Lange V. American reusable hospital pillows - a reservoir for hospital acquired pathogens: the importance of adequate decontamination. *J Infect Contr.* 2014; 42(6 Suppl): S34-S35. DOI: 10.1016/j.ajic.2014.03.097
125. Shik NF, Ford S, Thompson R, Pena M, Luchi M. The heat is on: control of community-acquired MRSA in a burn center. *Am J Infect Contr.* 2006; 34 (5): E100. DOI: 10.1016/j.ajic.2006.05.280
126. Mottar R, Roth M, Allen M, Gerber R, Gerber BR. Pillow talk: examining pillow cores in a regional burn center. *Am J Infect Contr.* 2006; 34(5): E107-E108. DOI: 10.1016/j.ajic.2006.05.078
127. Lippmann N, Lübbert C, Kaiser T, Kaisers UX, Rodloff AC. Clinical epidemiology of *Klebsiella pneumoniae* carbapenemases. *Lancet Infect Dis.* 2014 Apr;14(4):271-2. DOI: 10.1016/S1473-3099(14)70705-4
128. Lerner A, Adler A, Abu-Hanna J, Meitus I, Navon-Venezia S, Carmeli Y. Environmental contamination by carbapenem-resistant Enterobacteriaceae. *J Clin Microbiol.* 2013 Jan;51(1):177-81. DOI: 10.1128/JCM.01992-12
129. Airmid Health Group. Report ASCR092029: Pneumapure pillow. Airmid Health Group; 2013 Mar.
130. Tucker A, Dewhurst M. The Pillow is a Vector of Infection – A4 Poster v1. indd. Proceedings IPS 2012. 2012 Sep 24. Available from: <https://www.bolster.hr/wp-content/uploads/2023/06/The-Pillow-is-a-Vector-for-Infection-Tucker-Dewhurst-IPS-2012-Poster-Medical.pdf>
131. Simon D, Pauli G. Krankenversorgung und Instrumentensterilisation bei CJK Patienten und CJK-Verdachtsfällen. *Bundesgesundheitsblatt.* 1998; 41:279-85. DOI: 10.1007/BF03042975
132. Schulz-Schaeffer WJ. Infektionen durch Prionen. In: Kramer A, Assadian O, Exner M, Hübner NO, Scheithauer S, Simon A (Hrsg) Krankenhaus- und Praxishygiene. 4. Aufl. München: Elsevier; 2022. p. 136-41.
133. Harnoss JC, Dancer SJ, Kaden CF, Baguhl R, Kohlmann T, Papke R, Zygmunt M, Assadian O, Suhomel M, Pittet D, Kramer A. Hand antiseptics without decreasing efficacy by shortening the rub-in time of alcohol-based handrubs to 15 seconds. *J Hosp Infect.* 2020 Apr;104(4):419-24. DOI: 10.1016/j.jhin.2019.09.004
134. Lambe KA, Lydon S, Madden C, Vellinga A, Hehir A, Walsh M, O'Connor P. Hand Hygiene Compliance in the ICU: A Systematic Review. *Crit Care Med.* 2019 Sep;47(9):1251-7. DOI: 10.1097/CCM.0000000000003868
135. Zastrow KD, Kramer A. Therapeutic indications for local anti-infectives. Recommendations for isolation and antiseptic sanitation of patients with MRSA colonization or infection. *Dev Ophthalmol.* 2002;33:250-62. DOI: 10.1159/000065932
136. Chaberny IF, Wriggers A, Behnke M, Gastmeier P. Antibiotics: MRSA prevention measures in German hospitals: results of a survey among hospitals, performed as part of the MRSA-KISS module. *Dtsch Arztebl Int.* 2010 Sep;107(37):631-7. DOI: 10.3238/arztebl.2010.0631
137. Biologische Arbeitsstoffe im Gesundheitswesen und in der Wohlfahrtspflege. 2014, 4. Änderung 2018. Available from: <https://www.bgw-online.de/resource/blob/13696/f7d59061152e53c1b6a32ab254f6acd5/trba250-biologische-arbeitsstoffe-im-gesundheitswesen-und-in-der-wohlfahrtspflege-data.pdf>
138. Deutsche Gesetzliche Unfallversicherung. DGUV Information 203-084: Umgang mit Wäsche aus Bereichen mit erhöhter Infektionsgefährdung. 2016. Available from: <https://publikationen.dguv.de/widgets/pdf/download/article/3029>
139. Deutsche Gesetzliche Unfallversicherung. DGUV Vorschrift 3. Unfallverhütungsvorschrift Elektrische Anlagen und Betriebsmittel. 1979. Available from: <https://publikationen.dguv.de/widgets/pdf/download/article/1052>

140. DIN EN 62353 VDE 0751-1:2015-10. Medizinische elektrische Geräte. Wiederholungsprüfungen und Prüfung nach Instandsetzung von medizinischen elektrischen Geräten. Deutsche Fassung EN 62353:2014. Berlin: Beuth.
141. Polovich M, Olsen MM. Safe handling of hazardous drugs. 3rd ed. Oncology Nursing Society; 2018.
142. Polovich M. Safe handling q&A. Handling Linens Contaminated. 2020. Available from: [https://www.ons.org/sites/default/files/2020-03/ONS\\_HOPA\\_HandlingLinens.pdf](https://www.ons.org/sites/default/files/2020-03/ONS_HOPA_HandlingLinens.pdf)
143. Occupational Safety and Health Administration. Code of federal regulations. Title 29, Labor: Subpart: Z\_ Toxic and Hazardous Substances: Bloodborne Pathogens. 2014. Available from: <http://frwebgate.access.gpo.gov/cgi-bin/get-cfr.cgi?TITL=29&PART=1910&SECTION=1030&TYPE=TEXT>
144. Occupational Safety and Health Administration. Controlling occupational exposure to hazardous drugs. 2016. Available from: [https://www.osha.gov/SLTC/hazardousdrugs/controlling\\_occecx\\_hazardousdrugs.html#resources](https://www.osha.gov/SLTC/hazardousdrugs/controlling_occecx_hazardousdrugs.html#resources).
145. Heudorf U, Hofmann H, Kutzke G, Otto U. Bettenaufbereitung im Krankenhaus - Ergebnisse der infektionshygienischen Überwachung in Frankfurt/Main, 2009. Hyg Med. 2011;36-9.
146. Winkelmann C, Fleßa S, Kramer A. Wirtschaftlichkeitsanalyse der dezentralen Bettenaufbereitung im Vergleich zur zentralen Bettenaufbereitung und Schlussfolgerungen zur Optimierung in einem Krankenhaus der Maximalversorgung. GMS Krankenhaushyg Interdiszip. 2008;3(2):Doc17.
147. Commission for Hospital Hygiene and Infection Prevention (KRINKO); Federal Institute for Drugs and Medical Devices (BfArM). Anforderungen an die Hygiene bei der Aufbereitung von Medizinprodukten. Empfehlung der Kommission für Krankenhaushygiene und Infektionsprävention (KRINKO) beim Robert Koch-Institut (RKI) und des Bundesinstitutes für Arzneimittel und Medizinprodukte (BfArM) [Hygiene requirements for the reprocessing of medical devices. Recommendation of the Commission for Hospital Hygiene and Infection Prevention (KRINKO) at the Robert Koch Institute (RKI) and the Federal Institute for Drugs and Medical Devices (BfArM)]. Bundesgesundheitsblatt Gesundheitsforschung Gesundheitsschutz. 2012 Oct;55(10):1244-310. DOI: 10.1007/s00103-012-1548-6
148. Petow R, Calrow A. An audit of mattresses in one teaching hospital. Prof Nurse. 1996; 11:623-6.
149. Arbeitskreis Bettgestell- und Wagen Dekontaminationsanlagen. Maschinelle Dekontamination. 9. Aufl. 2022. Available from: [https://www.drweigert.com/fileadmin/Downloads/Prospekte/General/AK-BWA\\_Maschinelle\\_Dekontamination\\_Aufl9\\_2022\\_Ansicht.pdf](https://www.drweigert.com/fileadmin/Downloads/Prospekte/General/AK-BWA_Maschinelle_Dekontamination_Aufl9_2022_Ansicht.pdf)
150. Heintz M, Krämer J, Vossebein L. Risk analysis and biocontamination control - hygiene measures in commercial laundries. Tenside Surf Det. 2007; 44(5): 274-80. DOI: 10.3139/113.100348.
151. Vossebein L. Aufbereitung von Krankenhauswäsche. In: Kramer A, Assadian O, Exner M, Hübner NO, Scheithauer S, Simon A (Hrsg) Krankenhaus- und Praxishygiene. 4. Aufl. München: Elsevier; 2022. p. 516-9.
152. DIN EN 14065:2016-08. Textilien - In Wäschereien aufbereitete Textilien - Kontrollsystem Biokontamination; Deutsche Fassung EN 14065:2016. Berlin: Beuth; 2016.
153. RAL-GZ 992:2022-01. Sachgemäße Wäschepflege - Gütesicherung. Available from: <https://www.beuth.de/de/technische-regel/ral-gz-992/353236147>
154. British Healthcare Trades Association. Protect, Rinse and Dry BHTA guidance on care, cleaning and inspection of healthcare mattresses. 2012. Available from: <https://www.bhta.com/wp-content/uploads/2019/10/BHTA-3.pdf>.
155. Ying Q, Qun L, Qinzhong L, Mingliang C, Hong C, Ni Z. Investigation and control of a suspected nosocomial outbreak of pan-drug resistant in an intensive care unit. Open Med (Wars). 2016;11(1):587-92. DOI: 10.1515/med-2016-0096
156. Cezário RC, Duarte De Moraes L, Ferreira JC, Costa-Pinto RM, da Costa Darini AL, Gontijo-Filho PP. Nosocomial outbreak by imipenem-resistant metallo-beta-lactamase-producing *Pseudomonas aeruginosa* in an adult intensive care unit in a Brazilian teaching hospital. Enferm Infecc Microbiol Clin. 2009 May;27(5):269-74. DOI: 10.1016/j.eimc.2008.09.009
157. Valencia R, Arroyo LA, Conde M, Aldana JM, Torres MJ, Fernández-Cuenca F, Garnacho-Montero J, Cisneros JM, Ortíz C, Pachón J, Aznar J. Nosocomial outbreak of infection with pan-drug-resistant *Acinetobacter baumannii* in a tertiary care university hospital. Infect Control Hosp Epidemiol. 2009 Mar;30(3):257-63. DOI: 10.1086/595977
158. Bannatyne RM, Patterson TA, Wells BA, MacMillan SA, Cunningham GA, Tellier R. Hospital outbreak traced to a case of Norwegian scabies. Can J Infect Control. 1992;7(4):111-3.
159. Hosein IK, Hoffman PN, Ellam S, Asseez TM, Fakokunde A, Silles J, Devereux E, Kaur D, Bosanquet J. Summertime *Bacillus cereus* colonization of hospital newborns traced to contaminated, laundered linen. J Hosp Infect. 2013 Oct;85(2):149-54. DOI: 10.1016/j.jhin.2013.06.001
160. DIN 10113-2:2023-02. Horizontales Verfahren zur Bestimmung des Oberflächenkeimgehaltes und Nachweis von bestimmten Mikroorganismen auf Einrichtungs- und Bedarfsgegenständen entlang der Lebensmittelkette - Teil 2. Berlin: Beuth; 2023.
161. DIN EN ISO 18593:2018-10. Mikrobiologie der Lebensmittelkette - Horizontales Verfahren für Probenahmetechniken von Oberflächen. Berlin: Beuth; 2018.
162. Kramer A, Gruber B; Deutsche Gesellschaft für Krankenhaushygiene e.V. (DGKH), et al. S2k-Leitlinie Hygienische Anforderungen an Patientenbetten, Bettwäsche, Bettenzubehör und an den Personalschutz beim Umgang mit Betten, Registernummer 075-005. Berlin: AWMF online; 2024 Oct 03. Available from: <https://register.awmf.org/de/leitlinien/detail/075-005>
163. Suleyman G, Alangaden G, Bardossy AC. The Role of Environmental Contamination in the Transmission of Nosocomial Pathogens and Healthcare-Associated Infections. Curr Infect Dis Rep. 2018 Apr;20(6):12. DOI: 10.1007/s11908-018-0620-2
164. Szostak-Kotowa J. Biodeterioration of textiles. Int Biodeterior Biodegrad. 2004; 53:165-70. DOI: 10.1016/s0964-8305(03)00090-8
165. Gutarowska B, Michalski A. Microbial Degradation of Woven Fabrics and Protection against Biodegradation. In: Jeon HY, editor. Woven Fabrics. Rijeka, Croatia: IntechOpen; 2012. p. 268-96. DOI: 10.5772/38412

## Erratum

The disclaimer regarding the erratum for this article and its republication was added.

**Corresponding author:**

Prof. em. Dr. med. habil. Axel Kramer  
Institute of Hygiene and Environmental Medicine,  
University Medicine Greifswald, 17475 Greifswald,  
Walther-Rathenau-Str. 48, Germany, Phone: +49 172  
1774763  
axel.kramer@med.uni-greifswald.de

**Please cite as**

Kramer A, Seifert J, Gruber B, Abele-Horn M, Arvand M, Blacky A, Buerke M, Chaberny I, Deja M, Engelhart S, Eschberger D, Gerhardts A, Hedtmann A, Heider J, Jäkel C, Kalbe P, Luckhaupt H, Müller W, Novotny A, Papan C, Piechota H, Pitten FA, Reinecke V, Scheithauer S, Schilling D, Schulz-Schaeffer W, Sunderdiek U. S2k Guideline: Hygienic requirements for patient beds, bed linen, bed accessories and personal protection when handling beds. *GMS Hyg Infect Control*. 2025;20:Doc20.  
DOI: 10.3205/dgkh000549, URN: urn:nbn:de:0183-dgkh0005497

**This article is freely available from**  
<https://doi.org/10.3205/dgkh000549>

**Published:** 2025-05-16  
**Published with erratum:** 2026-06-18

**Copyright**

©2025 Kramer et al. This is an Open Access article distributed under the terms of the Creative Commons Attribution 4.0 License. See license information at <http://creativecommons.org/licenses/by/4.0/>.